JACK GRYNBERG AND ASSOCIATES Petroleum, Geological, Geophysical and Mining Engineers

(

(

---

1050 - 17th Street, Suite 1950 Denver, Colorado 80202 (303)572-1455

## DAILY DRILLING REPORT

			Prospect/Are	a <u>Eagle Cree</u>	k S.A.	
Operator:	Jack J. Grynber	g County:	Eddy	State: <u>New N</u>	lexico	
Well Name:	Federal "GR"		Well No.:	2		
Location: _	990 FSL 1650 ( <del>SE-S\/)</del>	FWLSection:	28 Twp:	17 S Rge:	25 E	
Elevations:		Crd: <u>3572</u>	DF:	KB:	3579	
Well Type:	Wildcat:	Dev	elopment:	Other:	ield Ext.	
Objective Zone(s): San Andres Depth:1450 <sup>+</sup>						
Contractor: Osbourn Drilling Co.						
Spud:6:0	0 p.m. 4/12/74	Completed:	7/21/74	Status:		

DATE	DEPTH	PROGRESS
4/12/74	0'	Rigging up rotary tools.
4/13/74	240'	Preparing to run surface casing. Spudded 6:00 p.m. on 4/12/74. Drilled 14 3/4" hole to 240'.
4/14/74	240'	WOC. Ran 7 joints 10 3/4" 32.75# casing. Set at 235'KB. Cemented with 175 sx Class "C" 2% CaCl. Good circ. throughout. Circ. out 10 sx cement. PD 4:30 p.m. 4/13/74.
4/15/74	925'	Drilling 9 7/8" hole. Drilled out below surface 5:00 p.m. 4/14/74. Lost circ. at 914'.
4/16/74	יווו	Stuck pipe. Sample top: San Andres 718'.
4/17/74	1111'	Fishing. Jarred loose entire string. Stuck again at 480' while coming out. Backed off and left top of fish at 210'. Preparing to wash over.
4/18/74	יווו	Laying down wash pipe. Washed over and recovered entire fish.
4/19/74	יוווו	Stuck pipe. Went in hole to TD. Pumped Mud and LCM into lost circ. zone at 914'. Started out of hole. Pipe stuck at 400'.
4/20/74	ירוון	Got fish out of hole. Started in hole with drill pipe to spot cement plug. Would not go beyond 400'. Went in with 7 7/8" bit and reamed to 960'. Came out of hole.
4/21/74	1111'	Lost circ. Went in hole to 520'. Spotted cement plug - 50 sx. Class 'C' - + 10# Gilsonite per sack & $\frac{1}{2}$ # Floseal + 2% Ammonia Cl hole would not load- Spotted 50 sx Class'C' at 450' - 25% Gilsonite + $\frac{1}{2}$ # Floseal - did not hold - came out - put on 9 7/8" bit- started reaming.
4/22/74	יווו	Lost Circ. Reamed to 750'. Set plug of 60 sx. gel + 10# Gilsonite per sack at 750'. Did not hold- Spotted 60 sx gel + 25# Gilsonite per sack at 720. Did not hold.
4/23/74	יווו	Lost Circ. Trying to Run 7" csg. San Andres. Reamed to btm. w/ no returns. Started reaming & washing at 400'. Worst spots @ 400', 650', 820' & 960'. Got to btm., ran out of water. Waited 2 hrs. D.P. stuck, washed loose of water & jars. Pulled bk. up to 500' went bk. to btm. Had to ream & wash @ 900' & 960'. Got to btm. out of water. WOW.
4/24/74	ינוו	Lost Circ. San Andres. D.P. stuck while waiting on water. Pumped D.P. loose w/ Halliburton. POH w/ 2 tight spots @ 960' & 540'. Went bk. to btm, washed out 1 bridge @ 540'. POH & started in w/ 7" csg. w/ jagged guide shoe & DV Too' @ 850' & 2 cement baskets hit solid obstruction @ 640'. Pulled csg. out and layed down casg.