Operator  
Well  
Unit  
API#  

$$30-01S - 21SC2$$
  
 $P/ug 60' - 0' 5uf$   
 $P/ug 546' - 350' TAG$   
 $(Pof + 592)$   
 $24y'''$   
 $10C 5xs$   
 $24y''''''' = 214C'$   
 $P/ug 2018'$   
 $P/ug 3018'$   
 $P/ug 3018'$   

TOPS Sabde - 4ce' # Sabde - 4ce' #

- Contact OCD 24 hrs. prior to any work done.
- Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug.
- \* Install dry hole marker as per Rule 202.B.2
- \* Plugs are to be set from point indicated up.
- \* Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated.
- \* Shoe and stub plugs will be 50' above and below shoe or stub and tagged.
- \* Surface plug will be from 0' 60'
- \* Where plugs are required, cement must be placed inside and outside of all casing string(s) in the correct footage or sacks required, if no cement exists.
- \* Plugs to be tagged will be indicated.