Form 9331 (May 1963)	DEPART	UNITED STA MEN OF TH	TES E INTERIO	OR (Other just		re- 5. LEA	Form approved. Budget Bureau No SE DESIGNATION AND	
		GEOLUGICAL S		N. M. O.	C, L, L		LC 029492-	
(Do not	SUNDRY NO t use this form for properties Use "APPLIC	CATION FOR PERMIT	epen or plug ba	IN WELLS ack to a different oposals.)	reservoir.		<u> </u>	
	GAS	······································				7. UNI	T AGREEMENT NAME	
2. NAME OF OF	WELL OTHER		. ,			8. FAU	M OR LEASE NAME	
Murphy	Minerals Co	proration	roleum	Building	-Twr St	TILE RO	binson Fede	-ral
Roswel	Ll, New Mexic	co 88201		REC			8	
See also spi	F WELL (Report location ace 17 below.)		ance with any	State requirement	EIVE		ELD AND POOL, OR WH ayburg-Jack	
At surface	1650 FWL	- 990 FSL 330 FNL Of	Unit N	SEP	- 0 10-	11. 81	SURVEY OR ABEA	
- 01	1 . 1			U. S. GEOLOU ARTESIA, N	2104	Se	c.25,T16S,I	R31E
796 14 PEEMIT NO.	1.5 16.57/6	15. ELEVATIONS (S	Show whether DF,	ARTESIA, N	EW MEXIC	EY 12. C	DUNTY OR PARISH 13.	STATE
11. 12. 11.			4168 GL	4177 KB	·	1	Eddy	NM
16.	Check A	Appropriate Box T	o Indicate N	ature of Notic	e, Report, c	or Other D	lata	
	NOTICE OF INT	ENTION TO:		l	SUB	SEQUENT RE	PORT OF:	
TEST WAT	ER SHUT-OFF	PULL OR ALTER CASI	NG	WATER SH			REPAIRING WELL	[]
FRACTURE SHOOT OR		MULTIPLE COMPLETE ABANDON*	·		TREATMENT OR ACIDIZING	x x	ALTERING CASING ABANDONMENT*	
REPAIR WI		CHANGE PLANS		(Other)	E · Report res	sults of mul	tiple completion on V	Vell
(Other)	DODUSED OF COMPLETED O	PERATIONS (Clearly st	ate all pertinen	Com	pletion or Reco	ompletion K	eport and Log form.)	
proposed nent to t	norused or completed o l work. If well is direc this work.) *	tionally drilled, give	subsurface locat	ions and measure	d and true ve	rtical depth	is for all markers and	1 zones perti-
8/20/75	Ran Gamma R shots/ft w3 another hol	1/8" casin e in tubing	ng gun-0 g. Rele	.41 inche ased pacl	es. Pr ker. S	essure hut in	for night	•
8/21/75	Spotted 250 frac. Fm. 30, 25,000# gals. break 1/2, 3/4, 1 pressure 33 complete 11 I.S.I.P. 30	broke slig 20/40 sand down) with and finis 00. Went :45 A.M. 8	htly @ 2 1, 3,570 100 lbs hed with to 3400. /21/75.	20 psi. gals.f Gypban 1 1/4 11 3 more	Treate lush (2 35. St b/gal. balls	d w/30 50 gal arted Dropp 3400 t	.sacid + w/l/4#/gal bed 3 balls to 3450 psi	3,570 , then with . Job
8/22/75	Perforated Spotted 250 pad then 3 L35. Dropp and 200 lb. between sta Job complet ISIP 1600 l certify that the coregoin) gal. 15% stages of ded 10 ball J145 temp age 2 and 3 ce @ 4:15 P .0" SIP 600	acid. F 14,000# s betwee orary p] . Good .M. 8/22	'm. broke sand w/R en Stage ugging a ball act	0900 edifrac 1 follo gent fo ion and	ps1. 30 an wed by ollowed good	Pumped 250 nd 50 lbs. 7 250 gal. 1 by 250 ga build up w	Gypban acid 1. acid ith J145.
SIGNED	AMR	une	TITLE	Agent		- <u>12</u>	DATE9/8/7	5
	ce for Federal or State	office use)						
			TITLE			<u></u>	DATE	
CONDITT	ONS OF APPROVAL, I	F ANY:				REC	EIVED	
XI	BEERING BER	*S	ee Instruction	is on Reverse S	ide	SEP	1 0 1975	
ACTIVIC F	Prof. E. et al.					a	. C. C.	

,

O. C. C.