## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Revised 1-1-

Dilling Cites	OIL CONSERVATIO	N DIVISION	WELL API NO.			
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	P.O. Box 208	8 .	30-015-21607	_		
	Santa Fe, New Mexico	87504-2088				
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Salia 10, 110W 1110W 1		STATE FEE AA	$\dashv$		
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.			
0.0.000	TICES AND REPORTS ON WEL	LS		4		
	DODOSAIS TO DHILL UK TO DEEFEN	Offi For mining	7. Lease Name or Unit Agreement Name	-		
	ERVOIR. USE "APPLICATION FOR PEI C-101) FOR SUCH PROPOSALS.)	RECEIVED				
1. Type of Well:			S. A. J. J. FO. Com	İ		
Ot	▼ OTHER	1010	City of Artesia EQ Com	-		
2. Name of Operator		JUN 30. 94	8. Well No.			
YATES PETROLEUM CORP	ORATION		Wildert	_		
2 Address of Operator		O. C. D.  ARTESIA, OFFICE	Eagle Creek Atoka Morrow/Lagie	١ ا		
105 South Fourth Str	ceet - Artesia, NM 88210	AKTESIA, OFFICE	Creek Permo Penn			
A Well Location		Tine and 1980	Feet From TheEast L	ine		
Unit Letter :	.650 Feet From The South	Line and				
	Township 17S	tange 25E	NMPM Eddy County	777		
Section 24	Township 17S R	DF, RKB, RT, GR, etc.)		///.		
	///////		<b>V</b> ////////////////////////////////////			
Char	ck Appropriate Box to Indicate	Nature of Notice, F	Report, or Other Data			
11.	INTENTION TO:	I SUI	BSEQUENT REPORT OF:			
NOTICE OF I	INTENTION TO:		ALTERING CASING			
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK		- [		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	NG OPNS. PLUG AND ABANDONMEN'	٠ ــــ		
PULL OR ALTER CASING	_ 7	CASING TEST AND	CEMENT JOB	_		
PULL OH ALTER CASING	· [	OTHER:				
OTHER:		t i and data in	rluding estimated date of starting any proposed			
12. Describe Proposed or Completed (	Operations (Clearly state all pertinent details	, and give pertinent dates, in	cluding estimated date of starting any proposed			
work) SEE RULE 1103.	abandon well as follows:					
	·					
1. Nipple up BOP. POOH with production string.						
2. Set CIBP at 8100' and cap with 35 of tement to locate the same and the same as the same						
3. Fill hole with 10.0 ppg salt gel containing 25", below top of Strawn at 7638'.						
4. Spot a 10 Sack Class "H" plug from 700-750 to isolate Cisco perforations 6530-6600'.						
6. Determine free point of 4-1/2 cashing.  CBL indicates top of cmeent at 5990'.  (1501 mlug in open hole) across 4-1/2" stub. Tag plug.						
CBL indicates top of cmeent at 5990'.  7. Spot a 50 sack Class "C" plug (150' plug in open hole) across 4-1/2" stub. Tag plug.  7. Spot a 50 sack Class "C" plug (150' plug in open hole) across 4-1/2" stub. Tag plug.						
7. Spot a 50 sack Class "C" plug (150' plug in open noie) across 4 1/2 mb.  8. Spot a 50 sack Class "C" plug from 5400-5250' to cover top of Wolfcamp. Tag plug.  8. Spot a 50 sack Class "C" plug from 4200-4050' to cover top of Abo. Tag plug.						
8. Spot a 50 sack Class "C" plug from 3400-3230 to cover top of Abo. Tag plug.  9. Spot a 50 sack Class "C" plug from 4200-4050' to cover top of Glorieta. Tag plug.						
9. Spot a 50 sack Class "C" plug from 4200-4050 to cover top of Glorieta. Tag plug. 10. Spot a 50 sack Class "C" plug from 2200-2050' to cover top of Glorieta. Tag plug. 11. Spot a 50 sack Class "C" plug from 1330-1160' to cover intermediate casing shoe at 1262'.  CONTINUED  CONTINUED						
11. Spot a 50 sack C	lass "C" plug from 1330-1	160' to cover in	CONTINUED			
m 1 -						
I hereby certify that the information abo	eve is true and complete to the best of my knowledge	D . 1 hd o	n Clerk <b>DATE</b> 6-29-94			
Kuster	lein	mre Productio	505-748-1471			
SIGNATURE /	1 1		TELEPHONE NO.			
TYPEOR PRINT NAME RUSTY K	Tein					
(This space for State Use)	^		→ / · · · · · · · · · · · · · · · · · ·			
. 1	1 1 1 1 1 1 .	GEOLOGI <b>ST</b>	7-13-94	<u></u>		
AMROVED BY MON	6 paly	GEOLOGI <b>ST</b>	DATE 7-13-94			

Submit 3 Copies o Appropriate District Office

## State of New Mexico Energy inerals and Natural Resources Department

rorm C-1~ Revised 1-1-89

WELL API NO.	
30-015-21607	
5. Indicate Type of Lease STATE	FEE XX

( DO NOT USE THIS FORM FOR P	TO ONL	WELLS EPEN OR PLUG BACK TO A	WELL API NO.  30-015-21607  5. Indicate Type of Lease STATE  6. State Oil & Gas Lease No.  7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL WELL	•	JUN 30 '94_	City of Artesia EQ Com  8. Well No.
4. Well Location		ARTESIA, OFFICE  Line and198	
Section 24	. 7.0	Range 25E whether DF, RKB, RT, GR, etc.)	
NOTICE OF PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	INTENTION TO:  PLUG AND ABANDON CHANGE PLANS	X REMEDIAL WORK COMMENCE DRIL CASING TEST AN	ALTERING CASING  LING OPNS. PLUG AND ABANDONMENT  D CEMENT JOB
CONTINUED FROM PREVI			casing integrity.

- 12. Pressure test intermediate casing to 500 psi to verify casing integrity.
- 13. Spot a 40 sack Class "C" plug from 420-270' across surface casing shoe at 369'.

  14. Spot a 25 sack Class "C" plug from 92'-surface.
- Install regulation abandonment marker. 15.

NOTIFY OCD (748-1283) 24 HOURS PRIOR TO COMMENCING PLUGGING OPERATIONS.

NOTIFY OCD (748-1283) 24 HOURS 1 KIOK 15	•	<del>-</del> .
I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE	edge md belief. πιε Production Clerk	DATE 6-29-94 505-748-1471 TELEPHONE NO.
TYPE OR PRINT NAME RUSTY Klein  (This space for State Use)		
AMROVED BY	TILE	DATE