Form 3160-5 (August 1999)

OCD - Artesi-

TED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

OMB No. 1004-)135

FORM APPRO /ED

Expires November 40, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. NM - 0219603

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

				7. 15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
CURMIT	IN TRIPLICATE - C	Other Instructions	on rovorco cido	7. If Unit or CA/Agreement, Name and/or No.					
	IN TRIFLICATE - C		on reverse side						
Type of Well Oil Well	X Gas Well	Other	(1/8/2016/5/5)	8. Well Name and No.					
2. Name of Operator	1			FEDERAL BZ COM #12					
Yates Petroleum Co	30-015-21625								
3a Address		3b. Phone No. (inclui	de area code RECEILE	10. Field and Pool, or Explora ory Area					
105 S. 4th Street - A	EAGLE CREEK/ STRAWN PERMO								
4. Location of Well (Footage, Se			25/4	PENN 11. County or Parish, State					
SECTION 21-T17S-R25E	ECTION 21-T17S-R25E 1980' FSL & 1980' FEL			11. County of Fallsh, State					
	EDDY, NEW MEXICO								
	PPROPRIATE BOX(ES	S) TO INDICATE NAT	URE OF NOTICE, REPORT	, OR OTHER DATA					
TYPE OF SUMISSION			TYPE OF ACTION						
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off					
Subsequent Report	Alter Casing	Fracture Treat	Reclamation	Well Integrity					
Final Abandonment Notice	Casing Repair	New Construction	Recomplete	Other					
	Change Plans	Plug and Abandon	X Temporarily Abandon						
	Convert to Injection	Plug Back	Water Disposal						
Yates Petroleum Corporation proposes to T/ A this well as follows: 1. MIRU PU; RU safety equipment. 2. Pump 2% KCL water down tubing as needed to ND wellhead & install BOP. 3. POH w/ tubing & downhole equipment. RU wireline; run gauge ring to 7364', make bit & scraper run if necessary. 4. Run & set 4.5" CIBP at the following depths: 7364' - cap w/ 35' cement (over Strawn perfs) 6630' - cap w/ 35' cement (over Canyon perfs) , 6342' - cap w/ 35' cement (over Wolfcamp perfs) 5. TIH w/ tubing; load hole w/ 2% KCL water w/ 1 gpt corrosion inhibitor. 6. Pressure test casing to 500 psi & record w/ chart for 30 min. 7. POH laying down tubing. ND BOP, install B 1 adaptor w/ ball valve - RD, move off. Call OCD in Artesia 24 hrs before commencing operations - 505-748-1283 Call BLM in Carlsbad 24 hrs before commencing operations - 505-887-6544									
Name (Printed/Typed Donna Clack Signature	nna Claes	SPACE FOR FEDE	Title Date 5/21/02 RAL OR STATE OFFICE	USE					
Approved by Conditions of approval, if any, are the applicant holds legal or equital			Title Poirroleum Er	Date 7/15/02					
applicant to conduct operations the		or lease Milicii would entitle the	(FO						