

1. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

DEC 29 1975

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Wildcat		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator Read & Stevens, Inc.		5. State Oil & Gas Lease No. -----
3. Address of Operator P. O. Box 2126, Roswell, New Mexico 88201		7. Unit Agreement Name -----
4. Location of Well UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROM East 11 16 South 26 East THE LINE, SECTION TOWNSHIP RANGE NMPM.		8. Farm or Lease Name Yates
15. Elevation (Show whether DF, RT, GR, etc.) 3379' GR - 3393' RKB		9. Well No. 1
		10. Field and Pool, or Wildcat Wildcat
		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8045', PBTD 2133'. Plugged and abandoned well as follows:

- On 10-28-75, unseated pkr. & BP. Pulled tubg., pkr. & BP
- Set 20 sx. cement plug across perfs 1963'-2040'.
- Remove tubg. head, weld on to 4 1/2" csg. & pull csg. slips. Cut 4 1/2" csg. @ 1437' RKB.
- On 10-29-75, pulled & laid down 33 joints 4 1/2" csg., total of 1428.06'.
- Set 35 sx. cement plug 1450'-1300'.
- Set 10 sx. cement plug 10' - surface.
- Installed regulation marker.
- Cut off anchors & cleaned location.
- Operations completed @ 12:00 noon, 10-29-75.
- Will notify when location ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. L. Anderson Jr. TITLE Agent DATE 12-23-75

APPROVED BY L. L. Williams TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: