

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLIC.
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 15007

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Continental-Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat Under

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

28-163-29E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

Byard Bennett

3. ADDRESS OF OPERATOR

7011 N. Camino Martin, Tucson, Az.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

Unit "A"

660' FNL & 660' FEL Sec. 28-163-29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3,645' G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Total Depth of well: 2,265'.

1/5/76

Plugged to Abandon well, pumped cement plugs as follows:

1,750' - 1,650' 28 sacks cement.
400' - 300' 35 sacks cement.
20' - 0' 7 sacks cement.

Filled well with heavy drilling mud between all plugs.

Reason for plugging: Formations running low, water encountered.

RECEIVED
JAN 21 1976
U. S. GEOLOGICAL SURVEY
ARIZONA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Byard Bennett

TITLE

Operator

DATE

1/19/76.

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side