CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Submit 3 Copies to Appropriate

District Office	1
DISTRICT J P.O. Box 1980, Hobbs NM 88241-1980 OIL CONSERVATION DIVISION 2040 Pacheco St.	WELL API NO. 30-015-21745
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease  STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
OUNDDY NOTICES AND DEDODES ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Washington 33 State
1. Type of Well: OIL GAS WELL OTHER	
2. Name of Operator	8. Well No. 18
ARCO Permian V	9. Pool name or Wildcat
3. Address of Operator P.O. Box 1089 Eunice. NM 88231	Artesia Queen Grbg SA
4. Well Location Unit Letter J: 1550   Feet From The S   Line and 25	11 Feet From The E Line
33 – 175 p 28E	NMPM Eddy County
Section 33 Township 1/3 Range 20L	
3662° GL	XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
TEMPORARIET ABANDON	
PULL OR ALTER CASING CASING TEST AND CE	EMENT JOB L
OTHER: Add San Andres Perts OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	
TD: 6404' PBD: 6015' PERFS: 2382-2996'  MIRU POH w/rods, tbg, & pmp Install BOP RIH & Set RBP above San Andres perfs @ 2382-2996'	
MIRU 6189 1011 12 13	
POH w/rods, tbg, & pmp Install BOP RIH & Set RBP above San Andres perfs @ 2382-2996' Circ. clean csg. Perf 1880-2124' Frac	
Install BOP	
RIH & Set RBP above San Andres perfs @ 2382-2996'	12 0 2
Circ. clean csg.	CENTESIN 53
Perf 1880-2124'	15 RELLARIU 3/
Frac	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
RIH w/wireline & set @ 1850' Perf 1462-1802' FracPull both RBP and return all perf zones to production. Downhole commingle not required.	
FracPull both RBP and return all perf zones to production. Downhole commingle not required.	
/	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE HULLE W. Mulle TITLE Administrative	Assistant DATE 04/05/99
TYPE OR PRINT NAME Kellie D. Murrish	те <b>l</b> ерноме мо. 505-394-1649
(This space for State Use)	
ORIGINAL SIGNED BY TIM W GUM  APPROVED BY DISTRICT II SUPERVISUR FOR TITLE	DATE 4-8-99