



6 PM

7

8

9

10

11

MIDNIGHT

12

1

2

3

4

5

6

7

8

9

10

11

NOON

GRAPHIC CONTROLS CORPORATION

CHART NO. MC MP-3000 75 DIV.
5-25-93

METER

CHART PUT ON

TAKEN OFF

LOCATION EAL F-371

REMARKS
UNIT LTR. "F"
2220 FNL 25FWL
Sec 3ST 175R28E

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
RECEIVED P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

AUG 16 '89

WELL API NO.
30-015-21806

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-11593

7. Lease Name or Unit Agreement Name

Empire Abo Unit "F"

8. Well No.
371

9. Pool name or Wildcat
Empire Abo

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
ARCO OIL AND GAS COMPANY ✓

3. Address of Operator
P. O. Box 1610, Midland, Texas 79702

4. Well Location
Unit Letter F : 2220 Feet From The North Line and 25 Feet From The West Line

Section 35 Township 17S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3672.9 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Recomplete same zone ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-10-89 RUPU. POH w/CA. WL set C1BP at 6170. Press test csg to 500#. Perf Abo f/6136-6145. Ran 2 7/8 tbg and pkr to 6042. Acidized w/1000 gals 15% HCL. Swabbed load. POH w/CA. WL set C1BP at 6117. Press test to 500#.
7-13-89 Perf Abo f/6090-98. Acidized w/1000 gals. Swabbed load. WL set C1BP at 6070. Press test to 500#.
7-14-89 Perf Abo f/6036-6044. Acidized w/1000 gals. Swabbed load. Well kicked off. Ran CA: 2 7/8 tbg & pkr to 5977.
7-18-89 Swab well & kicked off. RDPU.
7/19/89 In 24 hrs flow 103 BO, 7 BW, 1.2MMCF, 27/64" ck, tp-350#.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken W. Gosnell TITLE Engr. Tech. DATE 8-14-89

TYPE OR PRINT NAME Ken W. Gosnell 915/688-5672 TELEPHONE NO.

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY TITLE DATE AUG 17 1989

CONDITIONS OF APPROVAL, IF ANY: