

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-21826
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 647
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "E"
8. Well No. 391
9. Pool name or Wildcat EMPIRE ABO

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
ARCO OIL AND GAS COMPANY

3. Address of Operator  
BOX 1710, HOBBS, NEW MEXICO 88240

4. Well Location  
Unit Letter E : 135 Feet From The NORTH Line and 2657 Feet From The EAST Line  
Section 35 Township 17S Range 28E NMPM EDDY County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3681.9' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: TEMPORARILY ABANDON <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN

TD 6404'; Perfs: 6232-53'

- 7/13/90 MIRU DDPN N/O W/H BOP. Pick up tbg, RIH to tag PB. POH w/tbg, SN, PN and MA. RIH w/bit and scrapper to PB. POH w/tbg, bit and scrapper. SDOWE.
- 7/17/90 R.O. Picked up 5-1/2" CIBP. RIH w/CIBP and tbg. Set plug. POH w/1 jt tbg. Circulated well w/8.6# brine w/WT-675 chemical. Pressured up on well to 500#.
- 7/19/90 R.O. Well standing full of fluid. Press up to 500#. Held for 20 mins. No loss in pressure. POH w/tbg and packer laying down in singles. RDCL. CIBP set @ 6206.00'

Pressure test witnessed by Gary Williams/NMOCD. Chart attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Administrative Supervisor DATE 7/25/90  
TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-3551

(This space for State Use)

APPROVED BY GW 7-29-90 TITLE  DATE

CONDITIONS OF APPROVAL, IF ANY:

