

C15F
OP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
300 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504

RECEIVED

SEP - 8 1993

WELL API NO.	30-015-21892
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER P & A Well

Name of Operator
YATES PETROLEUM CORPORATION

Address of Operator
105 South 4th St., Artesia, NM 88210

Well Location
Unit Letter B : 330 Feet From The North Line and 2310 Feet From The East Line

Section 23 Township 17S Range 25E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3485' GR

1. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
Plugged and abandoned well as follows:

Part 10-2
9-14-93
P & A

Moved in and rigged up pulling unit. POOH and laid down 53 rods and pump. Nippled down wellhead and nipped up BOP. POOH with 43 joints of tubing. Ran tubing back in hole to 1445'. Spot 30 sacks Class "C" 2% CaCl₂. No returns out of 5-1/2" casing. Pulled 15 stands. TIH and tag top of cement at 1371'. Plug was too low. Spot 25 sacks Class "C" 2% CaCl₂ at 1371'. Pulled 15 stands. WOC 4 hours. TIH to 1371'. No tag. Spot 25 sacks Class "C" 2% CaCl₂ at 1371'. Pulled 15 stands. WOC 4 hours. TIH to 1371'. No tag. Spot 25 sacks Class "C" 2% CaCl₂. Pulled 15 stands. TIH and tag top of cement at 950'. Circulated hole with mud. Pulled tubing to 773'. Spot 25 sacks cement from 773-520'. Pulled tubing to 419'. Spot 25 sacks cement from 419-166'. Pulled tubing to 97'. Spot 10 sacks from 97' to surface. POOH. Cut off wellhead and installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 8-5-93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Rusty Klein TITLE Production Clerk DATE Sept. 3, 1993
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)
APPROVED BY [Signature] TITLE [Signature] DATE 1/10/94
CONDITIONS OF APPROVAL, IF ANY: