

clsf

NM Form 3160-5
(November 1983)
(Formerly 9-331)
Approved

MISSION

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved,
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ Plug and Abandon

2. NAME OF OPERATOR
McClellan Oil Corporation

3. ADDRESS OF OPERATOR
P.O. Drawer 730 Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
H - 1980' FNL & 330' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3704 GR

RECEIVED

NOV 1 1991

O. C. D.
DISTRICT OFFICE

5. LEASE DESIGNATION AND SERIAL NO.
LC-068677

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Hinkle Federal

9. WELL NO.
#4

10. FIELD AND POOL, OR WILDCAT
High Nitro Premier

11. SEC., T., R., M., OR BLK. AND
SURVEY OR ARMA
Sec. 9-T16S-R29E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data.

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☒
(Other)	☐		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10/3/91 Rig up pulling unit. Set CIBP at 2300'. Put 35' cmt on top with dump bailer.
Shot csg at 1000'. Could not pull csg. Called BLM and spoke to Tom Hare. Plug well as per verbal order.
Mixed 100 sx Class "C" and displaced cmt w/heavy gel H20.

10/4/91 Tagged cmt top at 652'. Perf 4½" csg at 390' and cmted with 100 sx Class "C" neat. Circulated cmt to surface.

Prep to finalize and rehab location.

Part ID-2
11-8-91
P & A

18. I hereby certify that the foregoing is true and correct

SIGNED Matthew Lee

TITLE Drig. & Comp. Engineer

DATE 10/11/91

(This space for Federal or State office use)

APPROVED BY _____

TITLE _____

DATE 10/31/91

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side