

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SEP - 7 '89

| |
|---|
| WELL API NO. 30-015-21963 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. B-2071-25 |
| 7. Lease Name or Unit Agreement Name Empire Abo Unit "F" |
| 8. Well No. 361 |
| 9. Pool name or Wildcat Empire Abo |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3668.2 GR |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|--|
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER | 2. Name of Operator ARCO OIL AND GAS COMPANY |
| 3. Address of Operator P. O. Box 1610, Midland, Texas 79702 | 4. Well Location Unit Letter H : 1765 Feet From The North Line and 1270 Feet From The East Line Section 34 Township 17S Range 28E NMPM Eddy County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3668.2 GR | |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Recomplete same zone ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-27-89 RU PU. POH w/CA. Set C1BP at 6200. Perf Abo f/6151-60. Acidize w/1500 gals. Swab test. Set C1BP at 6140. Perf Abo f/6116-26. Acidize w/1500 gals. Swab test. Set C1BP at 6100. Perf Abo f/6068-74. Acidize w/1500 gals. Flow test ARO 1.76MMCF, OBW, 0 BO, 730# TP, 22/64 ck. Ran CA: 2 3/8 tbq & pkr to 5994.

7-06-89 RD PU. Well shut in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken W. Gosnell TITLE Engr. Tech. DATE 8-31-89

TYPE OR PRINT NAME Ken W. Gosnell 915/688-5672 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY: [Signature]

MINE WILLIAMS

DISTRICT II

APPROVED BY: [Signature] TITLE DATE AUG 31 1989

CONDITIONS OF APPROVAL, IF ANY: