orm 9-331 May 1963)	I	AOC COPY UNI. STATES AENT OF THE INTI	SUBMIT IN TRIPLI (Other instructions Verse side)	on re-		roved. ireau No. 42–R1424 ON AND SERIAL NO.
	G	EOLOGICAL SURVEY	/		NM 070	
	his form for propos	CES AND REPORT als to drill or to deepen or p TION FOR PERMIT—" for su	lug back to a different reservoir.		IF INDIAN, ALLOI	TEE OR TRIBE NAME
			REGEI	VEP	UNIT AGREEMENT	NAME
OIL GAS WELL WEL						
NAME OF OPERATOR	R Call A	. Schellinger Trilling Company	APR 2.8	1978 ^{8.}	West F	
ADDRESS OF OPERA					WESL F	ederal
. LOCATION OF WELL See also space 17	. (Report location el	, Artesia, N.M learly and in accordance with		TFIGE	#1. FIELD AND POOL	
At surface				11	Wildc	
1980	0 from Nor	th line 1980	from East line Unit G		SURVEY OR A	n17S Rge2'
4. PERMIT NO.		15. ELEVATIONS (Show wheth	ner DF, RT, GR, etc.)	12.	COUNTY OR PAR	ISH 13. STATE
		3464.3	'GR	1	Eddy	N.M.
6.	Check Ac	propriate Box To Indica	te Nature of Notice, Repo	rt, or Other	Data	
	NOTICE OF INTEN	TION TO :	1	SUBSEQUENT	REPORT OF:	
TEST WATER SHU		PULL OR ALTER CASING	WATER SHUT-OFF		REPAIRI	WELL
FRACTURE TREAT		MULTIPLE COMPLETE	FRACTURE TREATMEN	IT		G CASING
SHOOT OR ACIDIZI	Е	ABANDON*	SHOOTING OR ACIDIZ	ING 🗙	ABANDON	MENT*
REPAIR WELL		CHANGE PLANS	(Other)	results of m	ultiple completi	on on Well
(Other)		[]	Completion or			
proposed work. nent to this wor	21-77 (P	onally drilled, give subsurface Premier Zone)	tinent details, and give pertinen lo cat ions and measured and tru	t dates, inclu e vertical dej	iding estimated oths for all mar	date of starting a kers and zones per
proposed work. nent to this wor Pe: KC of 6-1 Plu @	21-77 (P rf 1578-82 L water. oil and s 23-77 ug back to 1532-34, d	onally drilled, give subsurface Premier Zone) 2, 2 pf, .50 Je Swab back with sulpher water. 9 1530, set per	tinent details, and give pertiner locations and measured and tru t Charge, pump 1 very light show manent bridge pl ent with dump ba	t dates, inclu e vertical dep 2 bbls 7 of ga .ug wit	h wire 1 n top of	date of starting ar kers and zones perf A & bow .ine R1410
proposed work. nent to this wor 6-: Pe: KC: of 6-: Pln @ br 18. I hereby certify SIGNED	21-77 (P rf 1578-82 L water. oil and s 23-77 ug back to 1532-34, d idge plug,	<pre>onally drilled, give subsurface Premier Zone) 2, 2 pf, .50 Je Swab back with sulpher water. 0 1530, set per lump 30' of cem PBTD @ 1500' s true and correct </pre>	tinent details, and give pertiner locations and measured and tru t Charge, pump 1 very light show manent bridge pl ent with dump ba	2 bbls of ga ug wit	bing estimated puts for all mar . 15% NE s, rainb h wire 1 n top of Ap 4.5. Garesia, bio DATE	date of starting an kers and zones per CA & DOW

*See Instructions on Reverse Side