Submit 3 Conies		N7 ¹	cls	- ۲	<i>a</i> .
To Appropriate	State of New Energy Minerals and Natura		cri	Form Revised March 25	
District Office	Energy, Minerals and Natura	r Resources Department		UV Revised Watch 25	, 19
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240	OIL CONSERVAT	ION DIVISION	WELL API NO.		i
1025 N. Frederi Dr., 10005, NM 88240	2040 South I	Pacheco	30 0	015-2214	4
DISTRICT II	Santa Fe, NM	Pacheco 1 87595 ô 17 18 19 30 A 53	5. Indicate Type		
B11 South First, Artesia NM 88210		19-70-1 - 19-70-1		STATE 💭 FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		La ser Si	6. State Oil & Ga	is Lease No.	
SUNDRY NOTI	CES AND REPORTS ÔN	WELLS N	7. Lease Name or U	Jnit Agreement Name:	
UD NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO DEEPE	NOR PETIGRACK TO A	Potter Fe	d Cam	
DIFFERENT RESERVOIR. USE "APPLI	ICATION FOR PERMIT" (FORM Col	01) FOR SUCH PROPOSALS	TURER FE	a com	
1. Type of Well: Oil Well D Gas WellX		5 A 14	l.		
2. Name of Operator		1505020	9 Wall M-		
Murchison Oil & Gas,	Inc.	1600-	8. Well No. #1	0.	
3. Address of Operator			9. Pool name or V	Marrie	
1100 Mira Vista Blvd.	, Plano, TX 75093-469	18 (972)931_0700	Logan Drai		
Well Location				crust ingon	
	64.01	41 . A			
Unit letter <u>B</u> :	860' feet from the	North line and	1985'	feet from the <u>East</u> lin	ne
Section 29	T1	7S Range 27E	NTN 4001 4 1		,
	i o wiisinp	ther DF, BKB, RT, GR, etc.	NMPM t	Eddy County	
and the second second	Shelada	ZLC CA			
Ch	eck Appropriate Box to In-	dicate Nature of Notic	cc. Report or O	ther Data	
NOTICE OF INT	TENTION TO:		SEQUENT REI		
ERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING	С
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	•	PLUG AND	· _
ULL OR ALTER CASING		1		ABANDONMENT	
	MULTIPLE COMPLETION	CASING TEST AND CI	EMENT JOB 🔲	ABARDONNERT	
	COMPLETION -		EMENT JOB 🗖	ABARDONMENT	
THER:		OTHER.	_		Ē
OTHER: 2. Describe proposed or completed	COMPLETION	OTHER:	t dates including es	timoted data of stanting	
2. Describe proposed or completed proposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & b	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in	nt dates, including es posed completion or hole w/ Howc	timated date of starting an recompletion. 0 retrieving	
DTHER: 2. Describe proposed or completed proposed work). SEE RULE 110 RUPU & NUBOP, released tool & cleaned off & r get on packer. Wont d	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin	nt dates, including es posed completion or hole w/ Howc ag tool & was	timated date of starting an recompletion. o retrieving unable to	
2. Describe proposed or completed proposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & n get on packer. Went i retrieving tool & rele	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen	stimated date of starting an recompletion. To retrieving unable to t in hole w/	
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 1102 RUPU & NUBOP, released tool & cleaned off & n get on packer. Went is retrieving tool & rele & flowed for test. Per 	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer &	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen	stimated date of starting an recompletion. To retrieving unable to t in hole w/	Ē
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 1102 RUPU & NUBOP, released tool & cleaned off & n get on packer. Went is retrieving tool & rele & flowed for test. Per 	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer &	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen	stimated date of starting an recompletion. To retrieving unable to t in hole w/	Ē
2. Describe proposed or completed proposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & n get on packer. Went i retrieving tool & rele	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer &	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen	stimated date of starting an recompletion. To retrieving unable to t in hole w/	Ē
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 1102 RUPU & NUBOP, released tool & cleaned off & n get on packer. Went is retrieving tool & rele & flowed for test. Per 	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer &	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen	stimated date of starting an recompletion. To retrieving unable to t in hole w/	Ē
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & n get on packer. Went i retrieving tool & rele & flowed for test. Per 	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer &	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen	stimated date of starting an recompletion. To retrieving unable to t in hole w/	
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & n get on packer. Went i retrieving tool & rele & flowed for test. Per 	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer &	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen	stimated date of starting an recompletion. To retrieving unable to t in hole w/	
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & n get on packer. Went i retrieving tool & rele & flowed for test. Per 	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer &	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen	stimated date of starting an recompletion. To retrieving unable to t in hole w/	
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & n get on packer. Went i retrieving tool & rele & flowed for test. Per 	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer &	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen	stimated date of starting an recompletion. To retrieving unable to t in hole w/	
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & n get on packer. Went i retrieving tool & rele & flowed for test. Per 	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer &	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen	stimated date of starting an recompletion. To retrieving unable to t in hole w/	
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 1102 RUPU & NUBOP, released tool & cleaned off & n get on packer. Went is retrieving tool & rele & flowed for test. Per 	COMPLETION	OTHER: ent details, and give pertinen ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer &	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen	stimated date of starting an recompletion. To retrieving unable to t in hole w/	Ē
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & n get on packer. Went is retrieving tool & relee & flowed for test. Per up & test. Placed wel 	COMPLETION	OTHER: ent details, and give pertinent ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer & 2048' to 9057'. S 101.	nt dates, including es posed completion or hole w/ Howc ag tool & was packer & wen set @ 8970'. Wabbed & flow	stimated date of starting an recompletion. To retrieving unable to t in hole w/	
 DTHER: 2. Describe proposed or completed oproposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & nget on packer. Went is retrieving tool & rele & flowed for test. Per up & test. Placed wel 	COMPLETION	OTHER: ent details, and give pertinent ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer & 2048' to 9057'. S 101.	nt dates, including es posed completion or hole w/ Howc ag tool & was packer & wen set @ 8970'. Wabbed & flow	stimated date of starting an recompletion. To retrieving unable to t in hole w/	
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & n get on packer. Went is retrieving tool & rele & flowed for test. Per up & test. Placed wel 	COMPLETION	OTHER: ent details, and give pertinent ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer & 2048' to 9057'. S /01.	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen set @ 8970'. Wabbed & flow	stimated date of starting an recompletion. To retrieving unable to t in hole w/ Swabbed wed for clean	Ē
 DTHER: 2. Describe proposed or completed of proposed work). SEE RULE 1102 RUPU & NUBOP, released tool & cleaned off & r get on packer. Went is retrieving tool & rele & flowed for test. Per up & test. Placed wel hereby certify that the information abcomponent of the property of the second seco	COMPLETION	OTHER: ent details, and give pertinent ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer & 2048' to 9057'. S 101.	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen set @ 8970'. Wabbed & flow	timated date of starting an recompletion. The retrieving unable to t in hole w/ Swabbed wed for clean	ny ,
DTHER: 2. Describe proposed or completed or proposed work). SEE RULE 110: RUPU & NUBOP, released tool & cleaned off & released tool & cleaned off & released tool & released of the retrieving tool & released for test. Per up & test. Placed well between for test. Per up & test. Placed well hereby certify that the information about the information about the property of the formation about the information about the property of the formation about the information about the informating the information about the information about the info	COMPLETION	OTHER: ent details, and give pertinent ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer & 9048' to 9057'. S 101. of my knowledge and belief <u>E</u> Production Manual	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen set @ 8970'. Wabbed & flow	timated date of starting at recompletion. The retrieving unable to t in hole w/ Swabbed wed for clean DATE <u>4/12/01</u>	ny ,
DTHER: 2. Describe proposed or completed or proposed work). SEE RULE 1101 RUPU & NUBOP, released tool & cleaned off & n get on packer. Went is retrieving tool & rele & flowed for test. Per up & test. Placed wel hereby certify that the information about the inform	COMPLETION	OTHER: ent details, and give pertinent ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer & 9048' to 9057'. S 101. of my knowledge and belief <u>E</u> Production Manual	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen set @ 8970'. Wabbed & flow	timated date of starting an recompletion. The retrieving unable to t in hole w/ Swabbed wed for clean DATE <u>4/12/0/</u> (Sos) Telephone No. 613-	ny 39
DTHER: 2. Describe proposed or completed or proposed work). SEE RULE 1101 RUPU & NUBOP, released tool & cleaned off & n get on packer. Went is retrieving tool & rele & flowed for test. Per up & test. Placed wel hereby certify that the information about the inform	COMPLETION	OTHER: ent details, and give pertinent ach wellbore diagram of prop & packer, went in hole w. retrievin ill. Cleaned off hole w/ packer & 7048' to 9057'. S 101. of my knowledge and belief <u>Production Man</u>	nt dates, including es posed completion or hole w/ Howc ng tool & was packer & wen set @ 8970'. Wabbed & flow	timated date of starting an recompletion. The retrieving unable to t in hole w/ Swabbed wed for clean	ny

MURCHISON OIL AND GAS, INC. POTTER FEDERAL COM #1 SEC. 29, T-17S, R-27E 860' FNL AND 1985' FEL EDDY COUNTY, NEW MEXICO

