

at 3 Copies
Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

O. C. D.
ARTESIA, OFFICE

WELL API NO. 30-015-22226
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "F"
8. Well No. 333
9. Pool name or Wildcat EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator ARCO OIL AND GAS COMPANY	3. Address of Operator BOX 1710, HOBBS, NEW MEXICO
4. Well Location Unit Letter E : 1286 Feet From The WEST Line and 1602 Feet From The NORTH Line Section 34 Township 17S Range 28E NMPM EDDY County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3672.7' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: TEMPORARILY ABANDON <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN

TD 6319'; PERFS: 6170-6190'

06/07/91 MIRU DDPN ND WH NU BOP. UNSET TAC POH w/TBG, TAC, SN, PN, AND MA. PICK UP 4-3/4" BIT, 5-1/2" CSG SCRAPER, RIH w/BIT, SCRAPER AND TBG. POH w/TBG, SCRAPER, AND BIT. PICK UP 5-1/2" CIBP AND RUNNING GIH w/ CIBP, RUNNING TOOL, AND TBG. SET CIBP. POH w/1 JT TBG. SDON.

06/08/91 CIRCULATE WELL w/8.6# BRINE w/WT-675 CHEMICAL. CLOSE WELL IN. PRESSURE UP TO 500#. HELD FOR 15 MINS. RD KILL TRUCK. POH w/TBG AND CIBP RUNNING TOOL. ND BOP NU WH. LEFT 1 JT ON WH FLANGE. LAYED TBG DOWN IN SINGLES. RDCL. CIBP SET @ 6146.85'. PRESSURE TEST CHART ATTACHED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Administrative Supervisor DATE 6/13/91
TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 392-1600

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep DATE 4/21/91
CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary
Abandonment Expires 4/96

