

NO. OF COPIES RECEIVED		3
DISTRIBUTION		
SANTA FE	/	
FILE	/	✓
U.S.G.S.		
LAND OFFICE		
OPERATOR	/	

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

DEC 5 1977

**O. C. C.**  
ARTESIA, DEEDS

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-421	

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plug & Abandon		7. Unit Agreement Name
2. Name of Operator BEARING SERVICE & SUPPLY CO., INC.		8. Farm or Lease Name MWJ State
3. Address of Operator P.O. Box 100, ARTESIA, N.M. 88210		9. Well No. 1
4. Location of Well UNIT LETTER E 1650 FEET FROM THE FNL LINE AND 990 FEET FROM THE FNL LINE, SECTION 10 TOWNSHIP 17 RANGE 27 NEDEM.		10. Field and Pool, or Wildcat Und San Andres
15. Elevation (Show whether DF, RT, GR, etc.) GR 3402		12. County Eddy

**Check Appropriate Box To Indicate Nature of Notice, Report or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Nov. 30, 1977
2. Set 35 Sx Plug 1850'-1950' Class C 2% Cal.
3. Set 35 Sx Plug 1300'-1400' Class C 2% Cal.
4. Set 35 Sx Plug 650'-750' Class C 2% Cal.
5. Set 35 Sx Plug 350'-450' Class C 2% Cal.
6. Set 10 Sx Plug Top of Hole in 8 5/8"
7. Erected Dry Hole Marker
8. Halliburton used to pump cement
9. 36 Vis. fresh water mud used in between plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James Long TITLE President DATE 12-1-77

APPROVED BY Mikes Stuffed TITLE OIL AND GAS INSPECTOR DATE APR 6 - 1979

CONDITIONS OF APPROVAL, IF ANY: