NO. OF COPIES AFCEIVED		3.		Form C-103
DISTRIBUTION				Supersedes Ald C-102 and C-103
SANTA FE	17		NEW MEXROBIC CENSERVATION COMMISSION	Effective 1-1-65
FILE	17	~		
U.S.G.S.			MAR 27 1978	Sa. Indicate Type of Lease
LAND OFFICE			MAN 61 1010	State Error XX
OPERATOR	17			5. State Oll & Gas Lease No.
		·		
(DO NOT USE THIS FC USE	SU	NDR	Y NOTICES AND REPORTS ON WELLS posals to drill or to deepen or plug back to a different reservoir. Ion for permit -" (form C-101) for such proposals.)	
1. OIL GAB WELL WEL	. X		DTHER-	7. Unit Agreement Name
2. Name of Operator				8, Farm or Lease Name
BEARD OIL COMPAN	14 0			HAGSTROM
3. Address of Operator				9. Well No.
2000 Classen Cer	iter	, Sι	uite 200-S, Oklahoma City, OK 73106	#1
4. Location of Well				10. Field and Pool, or Wildcat
UNIT LETTER K			1983 FEET FROM THE South LINE AND 1992 FEET FROM	Wildcat
THE West	LINE, S	ECTIC	N 8 TOWNSHIP 17 South RANGE 24 East NMPM	
	///	())	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	$\overline{\eta}$	71	3818' КВ	<u> </u>
16.	Che	ck /	Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data
NOTI	CE C	F IN	ITENTION TO: SUBSEQUEN	T REPORT OF:
			_	
PERFORM REMEDIAL WORK			PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	]		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	_j.		CHANGE PLANS CASING TEST AND CEMENT JQB	
			OTHER	
OTHER				
17 Deserthe Proposed of C			perations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed

work) SEE RULE 1103.

Well was spudded at 10:00 P.M. 1-23-78. 13-3/8", H-40, 48# surface casing was set at 238' with 250 sacks Class "C" cement with 2% CaCl. Cement circulated. Waiting on cement time for 13-3/8" surface casing was 8 hours. Drilled  $12\frac{1}{4}$ " hole to 1107'. Ran 36 jts. 8-5/8", 24#, 8R, casing, set @ 1107'; cemented with 350 sacks Halliburton LtWt cement with 2% CaCl, followed with 200 sacks Class "C" cement with 2% CaCl. Cement did not circulate. Temperature survey found cement outside surface at 500'. Picked up 1" pipe and cemented with 50 sacks Class "C" cement with 2% CaCl; cement circulated. Waiting on cement time for 8-5/8" inter-w/4% CaCl. Checked top of cement and found it at 476'. Ran 1" and re-cemented with 200 sacks Class "C" cement with 2% CaCl; cement circulated. Waiting on cement time for 8-5/8" inter-mediate casing was 31 hours. Pressure tested casing to 1000 psi and casing held Okay. Well was drilled to a total depth of 7200'. Logs were run and  $4\frac{1}{2}$ ", 10.5# & 11.6#, new K-55 casing was set at 7160' and cemented with 300 sacks of Halliburton LtWt cement, followed with 360 sacks Class "C" cement. Waiting on cement time for  $4\frac{1}{2}$ " long string casing was 72+ hours. Ran Bond Log. Top of cement at approximately 4900'.

4<sup>1</sup><sub>2</sub>" casing was perforated from 4785-4786' and re-cemented with 200 sacks Class "C" cement. Waited on cement approximately 40 hours. Drilled cement; pressure tested to 2000 psi, held Okay. Cleaned out to PBTD. Ran Bond Log. Perforated 4 holes at 4710', cemented with 50 sacks cement. Maximum squeeze pressure 2500 psi, held Okay. SEE ATTACHED PAGE FOR CONT.

18. I hereby certify that the information above is tru	e and complete to the best of my knowledge and belief.	
BIENED - Comy While 1	Vice President	DATE
Amore Wa Gresset	SUPERVISOR, DISTRICT IL	MAR 2 7 1978
CONDITIONS OF APPROVAL, IF ANY		