

N.M.O.G.D. COPY  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY  
SUBMIT IN TRIPL  
(Other instructions  
reverse side)E  
re-Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-4028

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

RECEIVED

7. UNIT AGREEMENT NAME

AUG 07 1981

8. FARM OR LEASE NAME

Lark Federal

C.C.D.  
ARRESA, OFFICE

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Und.  
Diamond Mound - Grayburg11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 9, T-16-S, R-27-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR  
Collier Energy, Inc.

3. ADDRESS OF OPERATOR  
P.O. Box 798, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
1650' FNL & 1650' FWL  
Approximately 6 miles north of Riverside

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3433 Gh

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

## SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOT OR ACIDIZE ☐ABANDON\* ☒SHOOTING OR ACIDIZING ☐ABANDONMENT\* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐(Other) ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

It is our intent to plug and abandon the subject well in the following manner:

1. Spot 100' plug from top of Queen at approximately 600' to 700'.
2. Spot 100' plug across 8 5/8" casing shoe at 254'.
3. Spot ~~50'20"~~ plug to surface.
4. Will install dry hole marker, clean location and will notify when plugging and abandonment is completed for your inspection.

We intend to commence this plugging and abandonment within the next sixty (60) days.

RECEIVED  
JUL 17 1981OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Donald R. Cray

TITLE

President

DATE July 15, 1981

(This space for Federal use only)

APPROVED

APPROVED BY  
CONDITIONS

Rogers A. Chapman

TITLE

DATE

AUG 4 1981

JAMES A. GILLHAM  
DISTRICT SUPERVISOR

\*See Instructions on Reverse Side