FORM 3160-5 (June 1990)	DEPARTMEN	つ STATES		Ist Serecharch 31, 1993
Do not use this t	form for proposals to drill o	D REPORTS ON WELLS r to deepen or reenter a different res ERMIT -" for such proposals		5. Lease Designation 2834 al No. <i>NM-8436-A</i> 6. If Indian, Allottee or Tribe Name
	SUBMIT IN T	TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well	······································			8. Well Name and No.
Oil Well XWell		type other description or delete	L	Diamond Mound Fed. #1
2. Name of Operator		· · · · · · · · · · · · · · · · · · ·		9. API Well No. 30-015-22419
Oce		1	10. Field and Pool, or Exploratory Area	
3. Address and Telephone No.				Atoka
1001 Fannin, Suite 1600, Houston, TX 77002 (713) 265-6834				11. County or Parish, State
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FSL & 660' FWL NWSW Sec. 1, T16S, R27E				Eddy Co., NM
12.	CHECK APPROPRIATE	BOX(es) TO INDICATE NATURE (DF NOTICE,	REPORT, OR OTHER DATA
TYPE OF	SUBMISSION	TYPE OF ACTION		
X Noti	ice of Intent	Abandonment X Recompletion		X Change of Plans
Subsequent Report		Plugging Back		New Construction Non-Routine Fracturing
		Casing Repair		Water Shut-Off
Final Abandonment Notice		Altering Casing		Conversion to Injection
		Other		Dispose Water
		(Note: Report results of m		
13. Describe Proposed	or Completed Operations (Cle	Completion or Recompleti arly state all pertinent details, and give p	on Report and	a Log form.) s, including estimated date of starting any proposed
work. If well is direc	ctionally drilled, give subsurfac	e locations and measured and true verti	cal depths for	all markers and zones pertinent to this work.)*
Attempt recom	pletion to the Atoka, per ent and proposed schem	the attached procedure.		
				PECT NED DA
Signed Jun	at the foregoing is true and	Title Regulatory	Specialist	Date 01/29/01
(This space for Feder Approved by Conditions of approve	RIG. SGD.) LES BAB	YAK Title Title	um Engi	NEER JAN 81 2001
		knowingly and willfully to make to any departmen	t or agency of the	United States any false, fictitious or fraudulent statements or
representations as to any	matter within its jurisdiction.			

Diamond Mound Federal #1 1980' FSL & 660' FWL Sec. 1, T-16-S, R-27-E Eddy Co., NM

January 23, 2001 Recomplete to the Atoka

Current Production: Well TA'd Proposed Perfs: Atoka 8602-10' Anticipated Production Rate: 200 mcfpd

1) MIRU workover rig.

2

- 2) Kill well w/2% KCI water. ND tree and NU BOP's.
- 3) Release 4-1/2" Arrowset I pkr at 8063' & POOH w/tbg. Send pkr in for redress.
- 4) TIH w/tbg open-ended. Wash sand to CIBP at 8540'. Reverse circulate hole clean.
- 5) RU swab and swab fluid level down to 6000'. POOH w/tbg. RU choke manifold in flow line to frac tank.
- 6) RU sand line drill, or sand line wedge, and TIH. Knock out CIBP at 8540'. Chase junk to new PBTD at 8640'. POOH w/sand line drill.

a) May be underbalanced. Be sure to have enough lubricator for tool string.
b) Possible tight spots at 5089' and 5374'.

- 7) While diverting gas, TIH w/redressed pkr and on/off tool w/tailpipe as run before. Space out for 10-12 pts compression and set pkr at +8560'.
- 8) Test the Atoka. Swab for one day if necessary.
- 9) If the Atoka flows at commercial rates, load the annulus w/2% KCl packer fluid. ND BOP's and NU tree. RD workover rig and turn well over to Production. Obtain a gas sample for analysis and test well for State potential test.



