

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

3a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.

B-11593

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT ZONE. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator ARCO Oil and Gas Company	8. Farm or Lease Name Empire Abo Unit "E"
3. Address of Operator P.O. Box 1610, Midland, Texas 79702	9. Well No. 373
4. Location of Well UNIT LETTER <u>D</u> <u>150</u> FEET FROM THE <u>North</u> LINE AND <u>15</u> FEET FROM THE <u>West</u> LINE. SECTION <u>35</u> TOWNSHIP <u>17S</u> RANGE <u>28E</u> NMPM.	10. Field and Pool, or Wildcat Empire Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3670.4 GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Recomplete same zone</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

07/19/88 RUPU. POH w/CA. WL set CIGR at 6070. Perf Empire Abo f/6036 - 6046. Acidize w/1000 gals. Swab test. Set CIBP at 6025. Press test to 500#. Perf abo f/6002 - 6010. Set pkr at 6010. Acidize w/700 gals. Swab test kicked off flowing. RD PU 07/27/88.

07/29/88 In 24 hrs flowed 1 BO, 5 BW, 1034 MCF on 24/64 ck, 630# FTP. Shut well in to be used as monitor for pressure maintenance.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ken W. Sosnell TITLE Engr. Tech. 915-688-5672 DATE 08/05/88

APPROVED BY Mike Williams TITLE Original Signed By DATE AUG 10 1988

CONDITIONS OF APPROVAL, IF ANY: