

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**DISTRICT I**

P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**

P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-015-22464</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>Washington 33 State</b>
8. Well No. <b>26</b>
9. Pool name or Wildcat <b>Artesia Queen Grbg SA</b>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator <input checked="" type="checkbox"/> <b>ARCO Permian</b>	
3. Address of Operator <b>P.O. Box 1089 Eunice, NM 88231</b>	
4. Well Location Unit Letter <b>N</b> : <b>150</b> Feet From The <b>S</b> Line and <b>1650</b> Feet From The <b>W</b> Line Section <b>33</b> Township <b>17S</b> Range <b>28E</b> NMPM <b>Eddy</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3660' GL</b>	

11.

**Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: **DHC Yeso Production** ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6368' CIBP: 6025' PERFS: 2614-2974'

MIRUPU, POH w/rods & pmp. Install BOP. POH w/tbg. RIH w/bit & scraper. POH. Perf Yeso interval 3800-4110' OA. PPI Yeso perfs. POH w/2-7/8" WS, PU 3-1/2" WS, RIH w/tbg & pkr. Frac Yeso. Force close & flowback. POH LD 3-1/2" WS

Set RBP w/wireline above San Andres perfs 2614-2974' OA. Perf shallow sands 1300-2250' OA, PPI perfs. Frac down csg. Force close & flowback. Pull RBP. Run tbg & anchor. Remove BOP, Run rods, pmp, & hang well on.

Commingling has verbal approval from OCD.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Assistant DATE 04/20/99

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

**ORIGINAL SIGNED BY TIM W. GUM**  
**DISTRICT II SUPERVISOR**

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 5-6-99

CONDITIONS OF APPROVAL, IF ANY: