


- a. If productive kill well and run CA as per production supervisor.
- b. If non-productive. Kill well and POOH w/ packer and lay down WS. Set CIBP @ 5925'.

8. TOTPS


M. W. Gore

Concur:  R. D. Reynolds J. E. Shields