

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

C/SF
Oper.

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-22487
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. E-7842
7. Lease Name or Unit Agreement Name Empire Abo Unit "E"
8. Well No. 361
9. Pool name or Wildcat Empire Abo

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.")	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator ARCO Permian	
3. Address of Operator P.O. Box 1089 Eunice, NM 88231	
4. Well Location Unit Letter A 620 Feet From The N Line and 1200 Feet From The E Line Section 34 Township 17S Range 28E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3671.6' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ☐
PLUG AND ABANDON ☐	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6294' PBD: 6274' PERFS: 6020-6030' 4" liner @ 6058-6274'

09/08/99: NUBOP. TIH w/ RBP, retrieving tool on 2-3/8" tbg to 2800'. TOH. RIH w/bailer. Run 2-3/8" tbg to 6010'. Tag CIBP @ 6010'.

09/09/99: Notified NMOCD. Gary Williams present. Pmp 25 sx cmt plug 5920-5820'. Pull above plug to 5700'. Displace 5-1/2" csg volume w/32 Visc SW Gell. Spot Plug #2 @ 3475-3375' w/ 25 sxs "C" Neat cmt w/3X Calc Chloride. SI 3 hrs, WOC. RIH to 3485'. Did not tag #2 plug. Pull up to 3475'. Spot #3 plug w/50 sxs cmt.

09/10/99: Lower tbg to TOC @ 3330'. OK. Set cmt plug #4 @ 2193-2080'. TOH. Set cmt plug #5 @ 1100-1200'. TOH. Set cmt plug #6 @ 800-700'. SI 3 hrs. Tag TOC plug #6 @ 672'. NUBOP. Fill 5-1/2" csg 30' to surf. Well P&A'd 09/10/99.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Assistant DATE 09/22/99

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep I DATE 11-22-99

CONDITIONS OF APPROVAL, IF ANY: