

Submit 3 Copies  
to Appropriate  
District Office

**DISTRICT I**  
P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION RECEIVED**

**P.O. Box 2088**

Santa Fe, New Mexico 87504-2008 **MAY 20 1991**

**O. C. D.  
ARTESIA, OFFICE**

WELL API NO.

30-015-22524

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

647-349 647-351

7. Lease Name or Unit Agreement Name

Empire Abo Unit "F"

8. Well No.

321

9. Pool Name or Wildcat

Empire Abo

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

other

2. Name of Operator

ARCO OIL and GAS COMPANY

3. Address of Operator

P.O. Box 1610, Midland, Texas 79702

4. Well Location

Unit Letter H : 1610 Feet From The North Line and 250 Feet from The East Line

Section 33

Township 17S

Range 28E

NMPM Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3674.3 GR

11. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

(Other) ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

(Other) Temporarily Abandon ☒

12. Describe Proposed or completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-07-91. MIRU & P&A as follows:

Plug Interval Cmt Remarks

|   |           |        |   |
|---|-----------|--------|---|
| 1 | 5988-6210 | 35 sx  | CR at 6050. w/62' cmt on top                              |
| 2 | 5477-5718 | 25 sx  | Spot  |
| 3 | 2950-3500 | 60 sx  | Spot  |
| 4 | 1889-2134 | 25 sx  | Spot. Ran CCL f/1400-28                                   |
| 5 | 1125-1360 | 25 sx  | Spot. Perf at 700. Unable to pump into. Perf at 611. EIR. |
| 6 | 622-863   | 25 sx  | Spot  |
| 7 | 500-611   | 125 sx | Perf at 611. CR at 560 w/60' cmt on top.                  |
| 8 | 25-373    | 165 sx | Perf at 373.  |

\*Mike Williams & Johny Robinson w/NMOC changed procedure f/P&A to TA in order for monitor BH press build up. TA.

13. I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE

Ken W. Gosnell

TITLE

Regulatory Coordinator

DATE

5-16-91

TYPE OR PRINT NAME

Ken W. Gosnell

TELEPHONE

(915) 688-5672

(This space for State Use)

APPROVED BY

[Signature]

TITLE

Field Inspector

DATE

5/23/91

CONDITIONS FOR APPROVAL, IF ANY:

This Approval of Temporary  
Abandonment Expires 5/16/92