

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-22633
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Empire Abo Unit "H"
8. Well No. 295
9. Pool name or Wildcat Empire Abo
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator ARCO Permian
3. Address of Operator P.O. Box 1089 Eunice, NM 88231	4. Well Location Unit Letter M : 700 Feet From The S Line and 10 Feet From The W Line Section 33 Township 17S Range 28E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **Set CIBP & Add Perfs** ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6300' PBD: 6285' PERFS: 6050-6110'

07/22/97: POH w/tbg & pkr. RIH w/bit & scraper to 6217'

07/23/97: Set CIBP @ 6220'. Circ w/170 bbls 8.6# brine w/TH-377 chemical. Close BOP. Would not test.

07/24/97: Load w/4 bbls 8.6# brine. Test CIBP to 800#. Set pkr @ 6013.75'. Test 500#, OK.

07/25/97: Perf abo interval 6050-6080, 6080-6110'.

07/28/97: Acidize 6050-6110' w/2000 gals 15% HEFE HCL w/500 SCF/bbls N2.

07/29/97: Set 2-3/8" tbg @ 6000'. Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Administrative Assistant DATE 05/27/99

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

APPROVED BY Jim W. Genn TITLE District Supervisor DATE 6-2-99

CONDITIONS OF APPROVAL, IF ANY: