

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87501-2088

JUL 03 1991

WELL API NO. 30-015-22634
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name EMPIRE ABO UNIT "H"
8. Well No. 303
9. Pool name or Wildcat EMPIRE ABO

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator ARCO OIL AND GAS COMPANY
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240	4. Well Location Unit Letter <u>N</u> : <u>800</u> Feet From The <u>SOUTH</u> Line and <u>1340</u> Feet From The <u>WEST</u> Line Section <u>33</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>EDDY</u> County <u></u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3665.6' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: TEMPORARILY ABANDON ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TA & HOLD WELL BORE FOR FIELD BLOW DOWN

TD 6325'; PERFS: 6195' PENG0 TOOL w/SLIDING SLEEVE

6/19/91 MIRU. DDPU.

6/20/91 POH w/TBG AND SN. RIH w/4-3/4" BIT, 5-1/2" CSG SCRAPER. POH w/TBG, SCRAPER AND BIT. RIH w/5-1/2" CIBP. CIBP SET w/108 JTS IN THE HOLE. TRIED TO RESET CIBP INTO RUNNING POSITION. WOULD NOT RESET.

6/21/91 RU SANDLINE BAILER w/CHISEL POINT. PUSHED DOWN HOLE w/BAILER TO 4880'. POH w/SANDLINE BAILER. RIH w/4-3/4" BIT, 5-1/2" SCRAPER, AND TBG. PUSHED CIBP TO 6218'.

6/24/91 R.O. RIH w/5-1/2" CIBP, RUNNING TOOL, AND TBG. SET CIBP. POH w/8' TBG SUB AND 1 JT TBG. RU KILL TRUCK. CIRCULATE WELL w/8.6# BRINE w/WT-675 CHEMICAL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(CONTINUED ON BACK)

SIGNATURE James D. Cogburn  
TYPE OR PRINT NAME James D. Cogburn

TITLE Administrative Supervisor DATE 7/02/91

TELEPHONE NO. 392-1600

(This space for State Use)

APPROVED BY [Signature]

TITLE Field Rep

DATE 7/8/91

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary  
Abandonment Expires

(CONTINUED FROM FRONT PAGE)

6/24/91 CLOSE WELL IN. PRESSURE UP TO 500#. WOULD NOT HOLD PRESSURE. FLUID VERY GASSY. CIRCULATE TOTAL OF 120 BBLS. 8.6# BRINE TO TRANSPORT. CLOSE WELL IN. PRESSURE TO 600#. WOULD NOT HOLD. RIH w/1 JT TBG AND 8' SUB. TAG CIBP. SET DOWN 13 POINTS ON PLUG. POH w/8' TBG SUB AND 1 JT TBG. PRESSURE UP TO 660#. HELD FOR 10 MINS. NO LOSS IN PRESSURE. BLED WELL OFF. PRESSURE UP TO 660#. HELD FOR 20 MINS. NO LOSS IN PRESSURE. RD KILL TRUCK.

6/25/91 R.O. POH w/TBG AND RUNNING TOOL. LAYING TBG DOWN IN SINGLES. ND BOP. N/U W/H. LEFT 1 JT TBG ON w/H FLANGE. CIBP SET @ 6180.11'. PRESSURE TEST CHART ATTACHED.

EMPIRE ABO UNIT  
H 303

UNIT LTR N  
800 FSL 1340 FWL  
SEC 33 T 175 R 28E

NETS NUMBER
TIME PUT ON
DATE PUT ON

TIME TAKEN OFF
DATE TAKEN OFF

6-24-91