N.M.O.C.D. COPY

1

- COPY	
Form 9–331	Form Approved. Budget Bureau No. 42–R1424
Dec. 1973 UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM-7066
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME JUN 2 5 1981
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
(Do not use this form 10/ proposals.) reservoir, Use Form 9–331–C for such proposals.)	Wells Federal Wells Federal
1. oil gas XX other	9. WELL NO. CALLER CONTRACT CONTRACT
well well well	2
2. NAME OF OPERATOR	10. FIEDDOR WILDCAT NAME
Mesa Petroleum Co./ 3. ADDRESS OF OPERATOR	11. SEC., T., R., M., OR BLK. AND SURVEY OR
Midland TX (9/U)	
1000 Vaughn Bldg. / Midiality, 17 / 2010 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 11, T165, R27E
below.)	12. COUNTY OR PARISH 13. STATE
AT SURFACE: 2080' FILL & 1850 FEL AT TOP PROD. INTERVAL: Same	Eddy <u>New Mexico</u>
AT TOTAL DEPTH: Same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REPORT, OR OTHER DATA	3642' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	ູ ອີອີອີລະເ ຕຍິເຊີນນີ້ທີ່ເອ າກາ
FRACTURE TREAT	
SHOOT OR ACIDIZE	(NOTE: Report results) of multiple completion or zone change on term 9-380 + 1 R 1 R 1821
PULL OR ALTER CASING	
ABANDON*	avmediate casing Roswell, NEVE MEXICO
(other) Subcequent report of Bring Cliff up to moundation of goat a cases	
17 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent actions and	
including estimated date of starting any proposed work. If well is directionary climet, by a g g g g g g g g g g g g g g g g g g	
r = r = r = r = r = r = r = r = r = r =	
Work commenced 5/29/81. Moved in well servicing unit. Set FSG blanking plug in PN @ 8626'. Loaded tbg w/2% KCL; tested tbg & csg to 1000 psi-OK. Released on=off tool; @ 8626'. Loaded tbg w/2% KCL; tested tbg & kr @ 8626. Went in hole to 7400' w/3-7/8" bit.	
Work commenced 5/25/04/28 KCL; tested tbg & csg to 1000 ps1-0K. Refeased 3.7/8" bit. @ 8626'. Loaded tbg w/2% KCL; tested tbg & csg to 1000 ps1-0K. Refeased 3.7/8" bit. spotted 20' of sand on top plugged pkr @ 8626. Went in hole to 7400' w/3-7/8" bit. Ran csg inspection log from 7350-1550'. Perfed 2 .34" holes @ 6310'. Set pkr @ 5914'. Ran csg inspection log from 7350-1550'. Perfed 2 .34" holes @ 6310'. Set pkr @ 5914'.	
from 5850-1587'. Log indicated top of cmt @ 53 pkr @ 4900'. RU Halliburton. Pumped down tbg pkr @ 4900'. RU Halliburton. Jumped down tbg	into squeeze perts 6 5300 a broke cito
pkr @ 4900'. RU Halliburton. Pumped down tbg out 8-5/8" csg. Pumped 100 gals 15% acid foll	owed by 1300 SX hat roat the attents
Subsurface Safety Valve: Manu. and Type	Set @Ft.
18. I hereby certify that the foregoing is true and correct SIGNED Athy MUTAL DON TITLE Prod. Rec. Analyst DATE 6/16/81 ACCEPTED FOR RECORD	
ELB (This space for Federal or State office use)	
APPROVED BY	DATE DATE JUN 2 4 1981
APPROVED BY	
CONDITIONS OF APPROVAL IF ANY: XC: USGS(3),TLS,MEC,LAND,CENT RCDS,ACCTG,ED BANN,PARTNERS,EILE USSGEOLOGICAL SURVEY ROSWELL NEW MEXICO	
KO. COCCONTRACT KONTANT	
t Same in the state of the sta	

NM-7066, Wells Federal #2 Mesa Petroleum Co. Subsequent Report of Bring cmt up to intermediate csg. Cont'd from Page 1

salt, 4# gilsonite & 1/4# flocele + 100 sx Class "C" w/2% CaCl. Displaced cmt 200' below pkr. Circ 100 sx to pit; WOC. Pulled pkr out of hole. Picked up 3-7/8" bit & 2 3-1/8" DC & went in hole w/2-3/8" tbg. Tagged cmt @ 5014'. Drilled cmt from 5014-5312'; fell free; drilled stringers to 5355'. Tested csg to 500 psi-0K. Tagged cmt @ 5961'. Drilled cmt from 5961-6322'; fell free. Went in hole to 8626', reversed sand off pkr. Circ hole w/2% KCL wtr. Pulled bit & DC's out of hole. Picked up top portion of on-off tool & went in hole to 8616'. Swabbed tbg & csg to 6000' w/swab-tagged fluid. Waited 2 hrs;fluid level rose 400'. Loaded hole & pressured to 1000 psi-leaked to 600 psi in 5 min. Set pkr @ 6345' & tested csg below pkr to 2000 psi-OK. Tested csg above pkr to 1200 psi-leaked 200 psi/ min. Reset pkr to 6221'. Tested csg above pkr to 1200 psi-OK. Spotted 20' of sand on top of pkr at 8626'. Spotted 100 gals 15% HCL acid @ 6310'. Set pkr @ 5914'. Opened pkr by-pass & spotted 50 sx Class "C" w/.6% Halad 9 in tbg above pkr, closed by-pass & pumped 50 sx Class "C" w/2% CaCl @ 1 BPM & 2800 psi. Displaced cmt 196' below pkr @ 1/2 BPM & 3100 psi. Pulled pkr out of hole, picked up bit & DC's & went in hole. Tagged cmt at 6060'.Drilled cmt to 6320'; fell free, tested csg to 1000 psi-OK. Went in hole to 8601'. Reversed sand off pkr @ 8626'. Circ hole w/2% KCL wtr. Pulled bit & DC's out of hole.Picked up upper portion of on-off tool & seating nipple & went in hole to 8610'. Swabbed tbg & csg down to 6200'. Latched onto on-off tool. Pulled pkr set @ 8626'. Went in hole w/seating nipple on 2-3/8" tbg & landed @ 8706'. Made 4 swab runs, TP 200 psi, CP 400 psi. Turned down sales line.