

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION  
RECEIVED BY  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501  
MAR 27 1987  
O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-79

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
B-11593-B

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Empire Abo Unit "F"
2. Name of Operator ARCO OIL AND GAS COMPANY	8. Farm or Lease Name
3. Address of Operator P. O. Box 1610 Midland, Texas 79702	9. Well No. #376
4. Location of Well UNIT LETTER <u>E</u> <u>1335</u> FEET FROM THE <u>North</u> LINE AND <u>700</u> FEET FROM THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>17S</u> RANGE <u>28E</u> NMPM.	10. Field and Pool, or Wildcat Empire Abo
15. Elevation (Show whether DF, RT, GR, etc.) 3685.3 GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Recomplete same zone</u> <input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug off existing perms and add perms (same zone) and treat.

1. POH w/CA.
2. Set CIBP @ 6,215.
3. Perf Abo F/6,196-6,203 (16 holes)
4. Treat w/1,000 gals.
5. Swab test.
6. RIH w/CA & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ken W. Gosnell TITLE Engr. Tech. DATE 3-25-87

Original Signed By  
Mike Williams  
Oil & Gas Inspector

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

DATE MAR 31 1987

CONDITIONS OF APPROVAL, IF ANY: