Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

CONDITIONS OF APPROVAL, IF ANY:

OII CONCEDIVATION DIVICION

P.O. Box 1980, Hot	bbs, NM 88240	P.O. Box 2088 Santa Fe, New Mexico 87504-2088				WELL API NO. 30-015-22819		
P.O. Drawer DD, Artesia, NM 88210  DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410  SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS TO FIVED						5. Indicate Type of Lesse STATE X FEE		
						6. State Oil & Gas Lease No.		
						7. Lease Name or Unit Agreement Name		
1. Type of Well: Oil. Will. XX	QAS WELL	-101) ron 300r	OTHER		11-	EMPIRE	ABO UNIT "E"	,
2. Name of Operat	AND GAS COME	DANV		JUL	<u> 56,88</u>	1. Well No. 393		
3. Address of Oper		ANI				9. Pool same or	Wildcat	
L	, HOBBS, NEW	MEXICO 8	8240	`` ———————————————————————————————————	PSIA, OFFICE	EMPIRE		
4. Well Location Unit Letter	B: 110	O Feet From T	NORTH		Line and 225	60 Feet From	EAST	Line
Section	35	Township	17S	R	ange 28E	NMPM ED	DY	County
			686.1 G	whether	DF, RKB, RT, GR, etc.)			
11.	Check /		<del></del>		Nature of Notice, R	enort or Othe	- Marie	
N.	•	-	REPORT OF:					
PERFORM REMED	IAI WORK	PILIG AND	ABANDON		REMEDIAL WORK			
TEMPORARILY AB		CHANGE I			İ		ALTERING CASING	
	_	SHICE	Care	ب	COMMENCE DRILLING		PLUG AND ABAND	XONMENT L
					CASING TEST AND CEMENT JOB L  TEMPORARILY ABANDON -			
OTHER:			······		OTHER:	TAKILI ADAN	DON	X
12. Describe Propose work) SEE RUL	ed or Completed Operati E 1103.	ions (Clearly state	all pertinent de	esails, ar	d give pertinent dates, includ	ling estimated date of	starting any proposes	1
TA & HOLI	D WELL BORE F	OR FIELD	BLOW DOW	N				
7/19/90	MIRU DDPU	SDON						٠
7/20/90	R.O. Well Dead. N/D W/H N/U BOP. POH w/tbg, S.N., P.N. and M.A. RIH w/tbg, scrapper, and bit to top perf. POH w/tbg, scrapper, and bit. RIH w/5-1/2" CIBP and tbg. Set CIBP. POH w/l jt tbg. Circulate well with 8.6# brine w/WT-675 chemical. SDON.							
7/23/90	R.O. RU kill truck. Pressure up to 500#. Held for 15 mins. No loss in pressure. RD kill truck. POH w/tbg, laying down in singles and CIBP running tool. Left one joint on W/H flange. CIBP set @ 6124.90'.							
_	Pressure te	est 7/23/9	0 witnes	sed 1	by Mike Stubblef	ield w/NMO	CD. Chart a	ttached.
I hereby certify that the	information above is true	and complete to the b	est of my knowle	dge and 1	belief.			<del></del>
SIGNATURE	Lang Regi	han		17TL	Administrative	Superviso	r 7/25	/90
TOPE OR FRINT NAME	James D. Co	ogburn		•			TELEPHONE NO.	392-3551
(This space for State Us				- <del></del>				
Ha	a las. listlin	~1			_		7/27/	190
APPROVED BY	· · · · · · · · · · · · · · · · · · ·			mu	B ———————————	<del></del>	DATE	

