MARTIN YATES, III 1912 - 1985 FRANK W. YATES 1936 - 1986



S. P. YATES CHAIRMAN OF THE BOARD JOHN A. YATES PRESIDENT PEYTON YATES EXECUTIVE VICE PRESIDENT RANDY G. PATTERSON SECRETARY DENNIS G. KINSEY TREASURER

105 SOUTH FOURTH STREET ARTESIA, NEW MEXICO 88210 TELEPHONE (505) 748-1471

O. C. D. MJESIA, OFFICE

(ICT 14'88

RECEIVED

I, <u>JUANITA GOODLETT</u>, do certify that to the best of my knowledge the following deviation survey is correct and accurate.

WELL NAME	ARMSTRONG KS STATE COM #1, LC-2346 1980' FSL & 560' FEL, Sec. 16-T17S-R26E
Depth	Deviation
686'	1°
1420'	1 ¹ [°]
1594 '	1 ¹ ^o
2091'	1°
2575 '	1°
3075 '	1°
3575 '	3/4°
3746 '	1°
4246 '	3/4°
4752 '	1°
5248 '	1-3/4°
5465 '	1 ¹ / ₄ °
5868 '	1°
6335'	l°
6830'	3/4°
7314'	1-3/4°
7832 '	12"

The above deviation information was taken from the daily defiling reports dated March 1979. Capitan Drilling Company was the contractor for the above well.

Mitt 11

ˈJʉanita Goodl∮tt Production Supervisor

Dated: October 11, 1988

TD

8580'