

# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**GARY E. JOHNSON**  
Governor  
**Betty Rivera**  
Cabinet Secretary

**Lori Wrotenberg**  
Director  
**Oil Conservation Division**

*Underground Injection Control Program  
"Protecting Our Underground Sources of Drinking Water"*

~~23~~ Apr-02

**GRUY PETROLEUM MANAGEMENT CO.**  
PO BOX 140907  
IRVING, TX 75014-0907

SIX

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well must be **shut-in** immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that repairs will be attempted so that such operations may be witnessed by a field representative.

## ***MECHANICAL INTEGRITY TEST DETAIL SECTION***

**AID 24 STATE COM 001**

**30-015-22878-00-00**  
N-24-17S-28E

Active Salt Water Disposal Well

<b>Test Date:</b>	4/23/2002 10:38:51 AM	<b>Permitted Injection PSI:</b>		<b>Actual PSI:</b>	
<b>Test Reason:</b>	Initial Test	<b>Test Result:</b>	F	<b>Repair Due:</b>	7/27/2002
<b>Test Type:</b>	Std. Annulus Pres. Test	<b>FAIL TYPE:</b>	Other External Failure	<b>FAIL CAUSE:</b>	
<b>Comments on MIT:</b>	Injection begun in July 2001 and no initial MIT test performed as required by Admin Order SWD-804.				

Thank you for your prompt attention to this matter and your efforts in helping to protect our ground water

Sincerely,

Oil Conservation Division, District II

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. \* Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

5-7-02 Contacted Jerry Smith to set up MIT  
MIT 10:00am 5-9-02