

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-22905
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-8318
7. Lease Name or Unit Agreement Name W Spruck
8. Well No. 5
9. Pool name or Wildcat Red Lake Queen Grbg SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED SEP 24 1991 O. C. D. ARTESIA OFFICE
2. Name of Operator Marbob Energy Corporation ✓	
3. Address of Operator P. O. Drawer 217, Artesia, NM 82810	

4. Well Location Unit Letter F : 2310 Feet From The North Line and 2310 Feet From The West Line Section 24 Township 17S Range 27E NMPM Eddy County
--

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug and abandon as follows: Set cmt plug from 2250-2100'. Tag plug @ 2310'. Set cmt plug from 1600-1100'. Tag plug @ 1000'. Set cmt plug @ 900-800'. Set cmt plug @ 500-400'. Set surface plug. Install dry hole marker and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE <u>Robin Smith</u>	TITLE <u>Production Clerk</u>	DATE <u>9/20/91</u>
TYPE OR PRINT NAME <u>Robin Smith</u>		TELEPHONE NO. <u>748-3303</u>

(This space for State Use)		
APPROVED BY <u>John Robinson</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>10-1-91</u>
CONDITIONS OF APPROVAL, IF ANY:		

Plugging