

ATIANTIC RICHFIELD COMPANY Blow Out Preventer Program

	Empire Abo Unit "F"
Wall No.	364
Tanadana	

Location 1550 FNL & 750 FEL, Section 34, T-17-S, R-28-E

BOP to be tested before installed on well and will be maintained in good working condition during drilling. Al wellhead fittings to be of sufficient pressure to operate in a safe manner.