

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

C19K
Form C-103
Revised March 25, 1999

WELL API NO. 30-015-23007
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 647

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-100) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name: Empire Abo Unit "B"
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	8. Well No. <u>B-42</u>	
2. Name of Operator B-P America	9. Pool name or Wildcat Abo	
3. Address of Operator P.O. Box 1089 Eunice, New Mexico 88231		
4. Well Location Unit Letter <u>F</u> : <u>2109</u> feet from the <u>North</u> line and <u>1778</u> feet from the <u>West</u> line Section <u>25</u> Township <u>17S</u> Range <u>28E</u> NMPM <u>Eddy</u> County <u>NM</u>		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) KB -3684.6' GL 3671.4		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. PROCEDURE TO P&A. NO UP HOLE POTENTIAL.

1. MIRU NUBOP.
2. TIH & TAG CIBP @ 5978' & cap w/ 25 sxs. cmt.
3. Circulate hole w/9.5# salt gel mud.
4. PUH to 3712' & spot 25 sxs. cmt. @ 3712' to 3612'. Cover Glorieta.
5. PUH to 2700' & spot 25 sxs. cmt. @ 2700' to 2600'. Shoe plug. TAG.
6. PUH to 850' & spot 25 sxs. cmt. @ 850' to 750'. Shoe Plug. TAG.
7. PUH to 566' & spot 25 sxs. cmt @ 566' to 466'. Cover Yates.
8. PUH to 60' & spot 10 sxs. cmt. @ 60' to 0. Surface plug.
9. Cut off well head & anchors 3' BGL.
10. Clean up location. Set Dry Hole Marker.

Notify OCD 24 hrs. prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Asst. Admin. Asst DATE 07.22.02
Type or print name Kellie D. Murrish Telephone No. 505.394.1649
(This space for State use)
APPROVED BY [Signature] TITLE Field Rep ID DATE AUG 6 2002
Conditions of approval, if any: