Form 9-331 Drawer DD	Form Approved.
UNITED STATES Artesia, NM 88210	
	5. LEASE 8 50 00 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
DEPARTMENT OF THE INTERIOR	DEALULED
C/5F GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME TO BE
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME & MARE 1 2 1982
(Do not use this form for proposals to drill or to deepen or plug back to a different	#4 17 9 1 6 8 4
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASENAME OF CO. D. SINK FEDERAE
1. oil gas X other	ARTESIA OFFICE
Well Ottes	[9. WELL NO. 얼굴답고 그 얼볕씨
2. NAME OF OPERATOR	
MESA PETROLEUM CO.	10. FIELD OR WILDCAT NAMES
3. ADDRESS OF OPERATOR 1000 VAUGHN BUILDING/MIDLAND, TEXAS 79701	DIAMOND MOUNT GRAYBURG 3 5 5
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	SEC 9. T16S RZŽE B SEC
AT SURFACE: 1980' FSL & 660' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: SAME	EDDY SEE NEW MEXICO
AT TOTAL DEPTH: SAME	14. API NO. 44. 14. 14. 14. 14. 14. 14. 14. 14. 14
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
DECULECT FOR ADDROVAL TO: CHRESCOURNE DEPOST OF	3522' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	
FRACTURE TREAT	'7075250 - 6 \$ \$ 6 0 0 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
SHOOT OR ACIDIZE	<u> </u>
REPAIR WELL	(NOTE results of multiple completion or zone
PULL OR ALTER CASING	1982 Inhange on Form: 9-330.)
CHANGE ZONES	
ABANDON* 🖾 🗀 CIL&G	AS କ୍ରିଡ଼ିଆ କ୍ରିଡ଼ିଆ କ୍ରିଡ଼ିଆ 👸
(other) U.S. GEOLOĞIČ, ROSWELL, NEW	AL SURVEY 전 설계 및 발대는 변경 / MEXICO
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	
including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*	
NOTE: TD: 8550' PBTD: 1500' PRODUCTION	PERFS: 1300'1308'
Propose to commence P&A Operations on or about April 12, 1982 as follows:	
Set CIBP @ 1250' with 38 cement on top. will	DB or 250x min. thru tubing
Set 25 sx ''C'' at 400' to 300'.	
0 . 15 . wgw 1001	
Set 15 sx "C" 100' to surface and install dry	note marker.
mm5	HOBBS
(C: Ü\$\$S (6), TLS, CEN RCDS, ACCTG, MEC, REM , F	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED TIREGULATORY COORD	INATOB _{ATE} MARCH 4, 1982
APPROVED AS AMENDED	UATE
(Orig. Sgd.) PETER W. CHESTER	
APPROVED BY TITLETITLETOUR DITTURETOUR DITTURE	DATE S
MAK I 1 1302	
JAMES A. GILLHAM PISTRICT SUPERVISOR	を を を を を を を を を を を を を を
I HOUSE SOLEKADOK I	

ee Instructions on Reverse Side