

Submit 3 Copies  
To Appropriate  
District Office  
**DISTRICT I**  
1625 N. French Dr., Hobbs, NM 88240

**DISTRICT II**  
811 South First, Artesia NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department

**OIL CONSERVATION DIVISION**

2040 South Pacheco  
Santa Fe, NM 87505

c/51  
Form C-103  
Revised March 25, 1999

WELL API NO. 30-015-23588
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-4853
7. Lease Name or Unit Agreement Name:  State
8. Well No. 2
9. Pool name or Wildcat Wildcat

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other
2. Name of Operator RPM Energy, Inc
3. Address of Operator 613 Commercial Bank Tower, Midland, TX 79701
4. Well Location Unit letter <u>J</u> : <u>2310</u> feet from the <u>South</u> line and <u>1650</u> feet from the <u>East</u> line Section <u>16</u> Township <u>16S</u> Range <u>26E</u> NMPM <u>Eddy</u> County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/19/99

Ran 2 3/8" tubing to 1200'. Set 40 Sx plug @ 1200'. W.O.C.  
Ran tubing and tagged TOC at 1203'. Set 20 Sx cement plug at 1200. W.O.C.

4/20/99

Ran and tagged TOC at 1014'. Cut 4 1/2" casing at 660. Not free. Cut and pulled 4 1/2 " casing @ 455'.  
Ran tubing to 710'. Pumped 165 Sx cement. Circulated cement to surface.  
Erected dry hole marker. Cleared location.

Post 2-1200  
PFA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Stubblefield TITLE Field Rep. II DATE 2/4/2000

Type or print name Mike Stubblefield Telephone No. 748-1283

(This space for State use)

APPROVED BY Mike Stubblefield TITLE Field Rep. II DATE 2/4/2000

Conditions of approval, if any: