

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO. <b>30-015-23609</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>E-4199</b>
7. Lease Name or Unit Agreement Name:

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/> <b>Injection</b>	RECEIVED ARTESIA	BHWFU (Formerly Gulf West Mesa #2)
2. Name of Operator <b>Read &amp; Stevens, Inc.</b>		8. Well No. <b>19</b>
3. Address of Operator <b>P. O. Box 1518 Roswell, New Mexico 88202</b>		9. Pool name or Wildcat <b>Bunker Hill Penrose</b>
4. Well Location Unit Letter <b>D</b> : <b>660</b> feet from the <b>North</b> line and <b>660</b> feet from the <b>West</b> line Section <b>24</b> Township <b>16S</b> Range <b>31E</b> NMPM County <b>Eddy</b>		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>4388.2' GL</b>		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

11/12/02 Set CIBP @ 3,500', spot 25 sx on top 3,150'.  
11/13/02 Spot 15 sx @ 2,372'-2,162'.  
11/13/02 Perforated @ 1,972', could not pump into @ 1000#.  
11/13/02 Spot 25 sx @ 2,032'-1,663' & tag.  
11/14/02 Pulled 1,324' of 4 1/2" casing.  
11/14/02 Spot 50 sx @ 1,386'-1,147' & tag.  
11/14/02 Spot 40 sx @ 400'-246'.  
11/14/02 Spot 20 sx @ 60' to surface.

Install dry hole marker.  
Circulate 10# mud.  
Move in & rip location. Reseed with native grasses.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John C. Maxey, Jr. TITLE Operations Manager DATE 1-8-03

Type or print name John C. Maxey, Jr. Telephone No 505/622-3770  
(This space for State use)

APPROVED BY [Signature] TITLE Field Rep DATE JAN 24 2003  
Conditions of approval, if any