

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate\*  
(Other Instructions on reverse side) 8821

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-32585

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Logan Draw Yeso OT Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Logan Draw San Andres

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Section 20-17S-27E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

NAME OF OPERATOR

Yates Drilling Company

3. ADDRESS OF OPERATOR

105 South 4th Street, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface

1980' FNL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3374' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

6-15-87 Pulled rods, pump & tubing.

6-16-87 Drilled out plug @ 1875' and cleaned out to 2764'. Squeezed perforations 2711'-2715' with 25 sxs. class "C" cement below retainer @ 2684'. Left 60' of cement on retainer. Squeezed perforations 1757'-1839' with 50 sxs. class "C" cement below retainer @ 1713'. Left 25 sxs. cement on retainer. Spotted 10 sxs. plug from 255'-355'. Spotted 10 sxs. plug from 105'-to surface. Mud was spotted between all cement plugs. Erected surface marker. Location will be cleared of equipment and leveled.

ACCEPTED FOR RECORD

JUN 24 1987

SJS

CARLSBAD, NEW MEXICO

JUN 23 11 05 AM '87  
CARLSBAD RESOURCE  
AREA HEADQUARTERS

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED

*Karen J. Leishman*

TITLE Production Clerk

DATE 6-22-87

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Approved as to content of this report and  
liability under bond is retained until  
surface restoration is completed.

DATE

Post ID-2  
7-10-87  
PFA

\*See Instructions on Reverse Side