Form 3160-5 (August 1999)	DEPART	ED STATES T OF THE INTERIOR AND MANAGEMENT		st. 2 Avenue	FORM APPROVED OMB No. 1004-0135 irres November 30, 2000	
	SUNDRY NOTICES	AND REPORTS ON V		CIL I DLease Serial I	ND.	
Do not use this form for proposals to drill or to re abandoned well. Use Form 3160-3 (APD) for such			re-enter an	NM 054434 6. If Indian, Allot	NM 054434 6. If Indian, Allottee or Tribe Name	
				7. If Unit or CA/	Agreement, Name and/or No.	
SUBMIT	her Instructions o	n reverse side	SCR 344			
1. Type of Well			1.8 9 9 8 7 J	8. Well Name a		
Oil Well	X Gas Well	Other		9, API Well N		
2. Name of Operator	reportion		C	30-015-237		
Yates Petroleum Co 3a Address		3b. Phone No. (includ	le area code	10. Field and Po	ool, or Exploratory Area	
105 S. 4th Street - Artesia, NM 88210 505-748-1471					EEK/ STRAWN GAS	
4. Location of Well (Footage, Se	c., T.,R., M., or Survey Eescrip	otion)	1914 - E	11. County or P		
SECTION 27-T17S-R2	5E 660' FNL & 99	90' FWL				
				EDDY, NEW		
	PPROPRIATE BOX(ES) TO INDICATE NATU	JRE OF NOTICE, REPORT TYPE OF ACTION	, OR OTHER DAT	A	
TYPE OF SUMISSION				Water Shut-Off		
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)			
Subsequent Report	Alter Casing	Fracture Treat	Reclamation	Well Integrity		
Final Abandonment Notice	Casing Repair	New Construction	Recomplete	Other		
	Change Plans	x Plug and Abandon	Temporarily Abandon			
	Convert to Injection	Plug Back	Water Disposal			
directionally or recomplete horizon or provide the Bond No. on file wit completion or recompletion in a nu- reclamation, have been complete REVISED PLUGGING P 1. MIRU PU; RU safety e 2. Attempt to pull 4-1/2" of across the casing stub, p 3. Spot 50 sk Class C ce plug w/ tubing & reset if r 4. Spot 50 sk Class C ce w/ tubing & reset if neces 5. Spot 15 sk Class C ce 6. Remove all surface eq * PRIOR TO S TO GET DOWN Call BLM in Carlsbad 24	htally, give subsurface locations an h BLM/BIA. Required subsequent ewinterval, a Form 316C-4 shall be d, and the operator has determined ROCEDURE AS PER COI quipment. 1930' of 4-1/2" or asing that is parted @ 19 uil tubing up hole & revers ment plug from 1151-1251 necessary. ment plug from 310-410' a asary.	d measured and true vertical de reports shall be filed within 33 d e filed once testing has been cor that the site is ready for final ins IVERSATION W/ ALEX casing recovery will be a 30'. If we cannot pull case e circ tubing clean. WOO ' across intermediate ca cross surface casing sho harker per regulations. STUB PLUG / A ABOVE DERF Derations - 505-887-6544	IS SWABODA & MIKE HILL (ittempted. sing, free point & cut casing. Pi C. Tag plug w/ tubing & reset i using shoe. Pull tubing up hole & oe. Pull tubing up hole & revers APPROV. GENERA SPECIAL	Affact the Bond under which operations. If the operations all be filed only after all required YPC ENGINEER). UII the free casing Set f riecessary. & reverse circ clean.	r the work win be performed s results in a multiple irrements, including POH; WOC. Tag VOC. Tag plug TO NTS AND	
I hereby certify that the foregoing Name (Printed/Type Donna Clack Signature	na resist	2	Title Operations Technicia Date 7-3-02 RAL OR STATE OFFIC			
Approved by	IG. SGD.) ALEXIIS C.	SWOBODA		ENGINEER	Date JUL (18 2002	
Cond tions of approval, if any, at the applicant holds legal or equi- applicant to conduct operations	e attached. Approval of this notice able title to those rights in the subj thereon.	does not warrant or certify that ect lease which would entitle the	Office			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 12 2. make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious