

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. STA-NM-L6698

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name N/A
2. Name of Operator VIKING PETROLEUM, INC. /	8. Farm or Lease Name Grynberg 28 State
3. Address of Operator 1050 17th Street, Suite 1950, Denver, CO 80265	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>660'</u> FEET FROM THE <u>South</u> LINE AND <u>1980'</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>16 S</u> RANGE <u>24 E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3704' GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/9/82 Drilled 6" hole to 53' (no fresh water encountered). Released rig.

4/13/82 Prepare to plug and abandon: Fill hole with mud or ready mix. Set dry hole marker in cement, clean location. Verbal approval to plug the well given by W.A. Gressett 4/13/82.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nancy Stolzle TITLE AGENT DATE 4/13/82
NANCY STOLZLE, JACK GRYNBERG AND ASSOCIATES
W.A. Gressett TITLE OIL AND GAS INSPECTOR DATE APR 16 1982