Operator Marbob Energy **TOPS** Gillespie St #2 Well Unit В Section 27 Twnship 17 Range <u> 28</u> API# 30-015-23984 Yates 500 7 Rivers 800 Bowers 1100 Surface Plug Queen 1465 1680 Grayburg 1912 San Andres Contact OCD 24 hrs. prior to any work done. Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug. Install dry hole marker as per Rule 202.B.2 Plugs are to be set from point indicated up. Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated. Shoe and stub plugs will be 50' above and below shoe or stub and tagged. Surface plug will be from 0' - 60' CIRC Where plugs are required, cement must be placed inside and outside of all casing string(s) in the correct footage or sacks required, if no cement exists.

Plugs to be tagged will be indicated.

