

Form 3160-5 (June 1990)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

		LAND MANAGEMENT	5. Lease Designation and Serial No. LC-048491-A
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  Use "APPLICATION FOR PERMIT-" for such proposals  SUBMIT IN TRIPLICATE			6. If Indian, Allottee or Tribe Name
			7. If Unit or CA, Agreement Designation
. Type of			8. Well Name and No.
Uwell ☑ Well ☑ Other TA			Saunders A #11
	f Operator /		
SDX Resources, Inc.  3. Address and Telephone No. PO Box 5061, Midland, TX 79704 915/685-1761			9. API Well No. 30-015-24123
			10. Field and Pool, or Exploratory Area
			Red Lake, QN-GB-SA
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 440' FNL 2310' FEL Sec. 13, T17S, R27E, Unit C			11. County or Parish, State
			Eddy Co., NM
2.	CHECK APPROPRIATE BOX(	s) TO INDICATE NATURE OF NOTICE, REPORT, C	OR OTHER DATA
	TYPE OF SUBMISSION	TYPE OF ACTION	
	Notice of Intent	Abandonment	Change of Plans
	_	Recompletion	New Construction
	Subsequent Report	Plugging Back	Non-Routine Fracturing
		Casing Repair	Water Shut-Off
	Final Abandonment Notice	Altering Casing	Conversion to Injection
		Other TA	Dispose Water
			(Note: Report results of multiple completion on Well
I2 Decor	he Proposed or Completed Operations (Clearly	state all pertinet details, and give pertinent dates, including estimated date	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)  of starting any proposed work. If well is
8/24/0 8/27/0	onally drilled, give subsurface locations and med	state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this fl. Test csg to 500# for 30 min - held ok.  Witnessed by Don Early.	Completion or Recompletion Report and Log form.)  of starting any proposed work. If well is work.)*
8/24/0 8/27/0	onally drilled, give subsurface locations and mea 1 - Set CIBP @ 2000'. Circ hole w/pki 1 - Re-run csg test to 500# for 30 min	state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this fl. Test csg to 500# for 30 min - held ok.  Witnessed by Don Early.	Completion or Recompletion Report and Log form.)  of starting any proposed work. If well is
8/24/0 8/27/0 Chart	onally drilled, give subsurface locations and mea 1 - Set CIBP @ 2000'. Circ hole w/pki 1 - Re-run csg test to 500# for 30 min	state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this fl. Test csg to 500# for 30 min - held ok.  Witnessed by Don Early.	Completion or Recompletion Report and Log form.)  of starting any proposed work. If well is work.)*
8/24/0 8/27/0 Chart	onally drilled, give subsurface locations and mean of the control	state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this of the first csg to 500# for 30 min - held ok.  Witnessed by Don Early.  RECEIVED  OCD - ARTESIA	Completion or Recompletion Report and Log form.)  of starting any proposed work. If well is work.)*
8/24/0 8/27/0 Chart	1 - Set CIBP @ 2000'. Circ hole w/pki 1 - Re-run csg test to 500# for 30 min attached.  by certify that the foregoing is true and cortect ace for Federal or State office use)	state all pertinet details, and give pertinent dates, including estimated date asured and true vertical depths for all markders and zones pertinent to this of the first csg to 500# for 30 min - held ok.  Witnessed by Don Early.  RECEIVED  OCD - ARTESIA	Completion or Recompletion Report and Log form.)  of starting any proposed work. If well is work.)*

