STATE UP NEW MEXIC NERGY AND MINERALS DEPA		CONSERVAT P. O. BOX 2 SANTA FE, NEW M	2088 DE	CEIVED	Form C-101 Revised 10 SA. Indicate	Type of Luase
SANTAFE			NOV	5 1982	STATE	6 Gas Louno No.
DERATOR	+		0.	C. D	mm	11111111111
	N FOR PERMIT	TO DRILL, DEEPEN,			UUUU	
. Type of Work					7. Unit Agre	ement Name
Type of Well		DEEPEN			8. Farm or L	
	OTHER		SINGLE MU	ZONE		reek "BL"
Name of Operator Yates Petroleum	Corporatio	n V			9. Well No. 3	
Address of Operator	- '	00210		• 2		d Pool, or Wildcat reek (SA)
207 S. 4th, Arte					1111111	
Location of Well UNIT LETTE	RN	LOCATED 990	FEET FROM THE DOI	ath LINE		
2310 FEET FROM	THE West	LINE OF SEC. 23	17S HGE.	25E		
					12, County	
				<u> </u>	Eddy	the for the second
					HHHH	
	tittittitt	tttttttttt	19. Froposed Depth	19A. Formatio	3	20. fictury or C.T.
			1500'	San Ar	dres	Rotary
Llevations (show whether DF,	KT, etc.) 21A.	Kind & Status Plug. Bond	21B. Drilling Contractor		22. Approx	. Date Work will start
3500'	В	lanket	L&M #2		ASAP	·
		PROPOSED CASING AN	D CEMENT PROGRAM			
SIZE OF HOLE	SIZE OF CASI	NG WEIGHT PER FOO	T SETTING DEPTH	I SACKS OF	CEMENT	EST. TOP
14 1/2"	10 3/4"	30#	appr. 350'	200 sx		circulated
9 1/2"	7	<u>23</u> #	appr. 1150'	<u>700 sx</u>		circulated
6 1/4"	4 1/2"	9.5#	appr. 1500'	150 s>		circulated
will be run run and set	to shut of 100' below a string w	Andres test. f gravel and ca the Artesian will be run, pe	aving. 7" in Zone. If com rforated and	termedia mercial stimulat	ite casi product ed for	ng will be ion is production.
MUD PROGRAM	: FW gel a	and LCM to 1150	', (or dry dr	ill), wa	ter to	TD.
BOP PROGRAM	: BOP's wi	ll be installe	d on 7" casin	g and te	ested da	aily.
			DEDN	VAL VALID AIT EXPIRES ESS DRILLI	- ワ・ル・ビ	>_

complete to the best of my knowledge and belief.	alan an a	
Tule Regulatory Coordinator		
OIL AND GAS INSPECTOR	NOV 8 1982	
Notify R.M.O.C.C. in sufficient	DATE	
	Tule Regulatory Coordinator	

•	thecasing
---	-----------

NEV EXICO OIL CONSERVATION COMMISSIC WELL LOCATION AND ACREAGE DEDICATION PLAT RECEIVED

	Supersedes C-128
~~	Effective 1-1-65

		All distances	must be from	the outer boundaries	of the Section	NOV 5 1982
Perator	TROLEUM COR			ise Dallo (Troole		O. C. Dvell No.
nit Letter	Section	Township	£	agle Creek	County	ARTESIA, OFFICE
N	23	17 Sou	th	25 East	Edd	dy
ctual Footage L 990	ocation of Well: feet from the	South	line and	2310	feet from the	West line
ound Level Ele		Formation Andre	S Poo	Eagle Cre	ek (SÅ	Dedicated Acreage:
1. Outline			bject well	by colored penci	il or hachure	e marks on the plat below.
interest	and royalty).					ownership thereof (both as to work
dated by	nan one lease of communitization	different owner , unitization, for	ship is ded ce-pooling.	cated to the we etc?	ll, have the	interests of all owners been conse
Yes	No If	answer is "yes	;" type of co	nsolidation		
lf answe th is form	r is "no," list th if necessary.)	e owners and tr	act descript	ions which have	actually be	een consolidated. (Use reverse side
No allow	able will be assig	gned to the well e)or until a non	until all int -standard un	erests have bee it, eliminating s	n consolidat such interest	ted (by communitization, unitizati ts, has been approved by the Comm
			<u> </u>			CERTIFICATION
						I hereby certify that the information c tained herein is true and complete to best of my knowledge and pelief.
	+ ! !			(Name Ken Beardemphi Position
						Regulatory Coordinat Company Yates Petroleum Corp Date
	1			1		11/5/82
					· ·	ROFESSIONA
231	oʻ					Date Surveyed November 4, 1982
	FEE	99		 		Registered Professional Engineer and/or Land Surveyor
••••	· · · · · · · · · · · · · · · · · · ·	1				Certificate No.
330 660	190 1320 1650 19	80 2310 2640	2000	1500 1000	500 O	NM PE&LS #5412



THE FOLLOWING CONSTITUTE MINIMUM BLOWOUT PREVENTER REQUIREMENTS

- 1. All preventers to be hydraulically operated with secondary manual controls installed prior to drilling out from under casing.
- 2. All connections from operating manifolds to preventers to be all steel. Hole or tube a minimum of one inch in diameter.
- 3. The available closing pressure shall be at least 15% in excess of that required with sufficient volume to operate the BOP's.
- 4. All connections to and from preventer to have a pressure rating equivalent to that of the BOP's.
- 5. Hole must be kept filled on trips below intermediate casing.