

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	☒
FILE	☒
U.S.G.S.	☒
LAND OFFICE	☒
OPERATOR	☒

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

RECEIVED BY

FEB 24 1987

Form C-103
Revised 10-1-77

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTRY OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (Form C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5a. Indicate Type of Lease State ☒ Free ☐
2. Name of Operator Morexco, Inc. ✓	5. State Oil & Gas Lease No. V-482
3. Address of Operator P. O. Box 481, Artesia, NM 88211-0481	7. Unit Agreement Name
4. Location of Well UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM East LINE, SECTION 1 TOWNSHIP 17S RANGE 28E N.M.P.M.	8. Farm or Lease Name Comet State
15. Elevation (Show whether DF, RT, GR, etc.) 3683' 2GR	9. Well No. #1
	10. Field and Pool or Wildcat Und.-G. Jackson SR-Q-GR-SA
	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPMS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER Re-entry operations and completion ☒
ALTERING CASING ☐
PLUG AND ABANDON ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-28-87 Remove dry hole marker.
1-29-87 Move in cable tool rig and begin drilling top plug.
2-03-87 Drilling on second cement plug.
2-05-87 Drilling on third plug.
2-06-87 T.D. at 2476'. Move off cable tool.
2-10-87 Rig up pulling unit and run CBL.
2-11-87 Perforate 2360-79 w/11 shots. Acidize w/1500 gallons of 15% NEFE.
2-12-87 Frac w/20,000 gallons of gelled 2% KCL and 30,000# sand.
2-14-87 Pump well.
2-15-87 Pump well.
2-16-87 Pump well.
2-17-87 Swab load off. Good show of gas.
2-18-87
2-19-87 Pump well and prepare for gas test.
2-20-87
2-21-87
2-22-87
2-23-87

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Geologist

DATE 2-23-87

APPROVED BY

Original Signed By
L. A. Clements

TITLE

DATE

MAR 27 1987