

Diamondback Pet
W Martba #1

L - 7-17-28

On February 5-1983 from 1974 was to 850:
circulated cement to surface.

3-12-83 TDwell 2 2375 Pipe 4 1/2" up to
12 1/2" up to 3000 ft. but did not cement
to surface. TOC found 6.65%. Run 1" &
circulate out to surface.

Excess completion of well 2-14-83 in the
bedrock from casing surface.

Allowable well cement effective
January 1, 1986.

Last production reports May 1985

Refer to bond pay for well.

It might add the pump rod has
been cemented for the well.

