

United States Department . . the Interior

OFFICE OF THE SECRETARY Minerals Management Service ROSWELL DISTRICT

SPECIAL APPROVAL STIPULATIONS

THE FOLLOWING DATA IS REQUIRED ON THE WELL SIGN

YATES PETROLEUM CORPORATION 13 Federales "BO" NW4NE4 sec. 22, T.17S., R.25E. Eddy County, New Mexico Lease No. NM-036191

THE SPECIAL STIPULATIONS CHECK MARKED BELOW ARE APPLICABLE TO THE ABOVE-DESCRIBED WELL AND APPROVAL OF THIS APPLICATION TO DRILL IS CONDITIONED UPON COMPLIANCE WITH SUCH STIPULATIONS IN ADDITION TO THE GENERAL REQUIREMENTS. EACH PERMITTEE HAS THE RIGHT OF ADMINISTRATIVE APPEAL, TO THESE STIPULATIONS PURSUANT TO TITLE 30 CFR 290.

A.	The Minerals Management Service office is to be notified at:
	$(505) \frac{624-790}{522-1332}$ Roswell
	(505) 7 56 9038 Artesia 746- 9838
	(505) 393-5146 Hobbs
	in sufficient time for a representative to witness:
	Spudding
	2. Cementing casing
	_ <u>/0</u> 7inch
	inch
	45 inch

- At least one working day prior to constructing the well pad, access roads Β. and/or related facilities, the operator or dirt contractor shall notify the authorized officer of the surface management agency. The surface management agency may be contacted at:
 - BLM phone (505) 887-6544 Carlsbad, New Mexico
 - BLM phone (505) 622-7670 Roswell, New Mexico

He shall also notify the surface management agency within two working days after completion of earth-moving activities.

Roads in the area of operation of this authorization will require surfacing.

and cement circulated to the surface. If surface casing is set at a lesser depth, casing must be cemented from the casing shoe to the surface or the cemented to the surface through a stage tool set at least 50 feet below the top of the Rustler after cementing around the shoe with sufficient cement to fill to the base of the salt section.

Before drilling below the _____ casing, the blowout preventer assembly will consist of a minimum of one-annular type and two ram type preventers. Minimum required fill of cement behind the _____ casing is to CUX culotte

□ 3.

BOP tests

After setting the _____casing string and before drilling into the salurad formation, the blowout preventers and related control equipment shall be pressure tested to rated working pressures by an-independent-service. -company. Any equipment failing to test satisfactorily shall be repaired or replaced. This office -notified in sufficient-time