

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

dsf

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR **READ: STEVENS INC.**
3. ADDRESS OF OPERATOR **P.O. Box 1518, Roswell NM 88202**
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
2970' FSL ± 990' FWL
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3803.2 GL

5. LEASE DESIGNATION AND SERIAL NO.
NM-18226
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
LYLE FED
9. WELL NO.
1
10. FIELD AND POOL, OR WILDCAT
WILDCAT SAN ANTONIO
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
SEC 5-163-30E
12. COUNTY OR PARISH
EDDY
13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Notify BLM 24 hrs prior to P!A
Set 100' cmt plug from bottom perf @ 1,950' to 1,850'.
Set 100' cmt plug 1,240' to 1,140' (across salt)
Perf two holes 50' below surface csg shoe of 507'.
Line cmt up ^{5 1/2"}12 1/4" x 8 7/8" annuls to surface, leave
5 1/2" csg full of cmt.
~~Set 50' cmt plug~~, install dry hole marker.
tag plugs w/ log, all fluid will be mud laden.

per verbal conversation w/ Shannon Shaw 5-2-90 jam

18. I hereby certify that the foregoing is true and correct

SIGNED John C. Meezy Jr. TITLE Pet Engr. DATE 5-2-90

(This space for Federal or State office use)

APPROVED BY Shannon J. Shaw TITLE Asst. Dir. DATE 5-24-90
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side