

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088 NOV 05 1984  
SANTA FE, NEW MEXICO 87501

O. C. D.  
ARTESIA OFFICE

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Gable FV
3. Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 2
4. Location of Well UNIT LETTER G 2310 FEET FROM THE North LINE AND 1650 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 17S RANGE 25E NMPM.	10. Field and Pool, or Wildcat Eagle Creek SA
11. Elevation (Show whether DF, RT, GR, etc.) 3596' GR	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☒  
CHANGE PLANS ☐  
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Production has declined below economic limit and as there is no apparent indication of workover economics, we propose to plug and abandon this well as follows:

1. Rig up unit and pull sucker rods and pump.
2. Swab tubing for static fluid level as near as possible to seating nipple.
3. Pull tubing.
4. Dump Ready-Mix cement, with controlled flow to prevent bridging, until casing is full.
5. Weld marker to casing.
6. Grade and level location, cut all anchors below ground level and haul away all equipment.

Will notify NMOCD prior to beginning any of the above operations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Juanita Goodlett TITLE Production Supervisor DATE 11-1-84

APPROVED BY M. L. Walker TITLE OIL AND GAS INSPECTOR DATE NOV 06 1984  
CONDITIONS OF APPROVAL, IF ANY: Notify NMO, C.C. in sufficient time to witness