

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

FEB 28 1992

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

O. C. D.  
ARTESIA OFFICE

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other P&A

2. Name of Operator

YATES PETROLEUM CORPORATION / (505) 748-1471

3. Address and Telephone No.

105 South 4th St., Artesia, NM 88210

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit E, 2310' FNL, 990' FWL, Sec. 28-T17S-R25E

5. Lease Designation and Serial No.

NM 12832

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Federal CD #6

9. API Well No.

30-015-24631

10. Field and Pool, or Exploratory Area

Eagle Creek SA

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plugged and abandoned well as follows:

2-12-92. POH w/55 - 5/8" rods and pump.

2-13-92. RIH w/CIBP at 1120'. Circulate hole with mud. Spot 5 sx cement on CIBP @ 1120'.

POH w/tubing to 385. Circulate 30 sx cement from 385' to surface. POH w/tubing. Cut wellhead off. Install dry hole marker.

WELL PLUGGED AND ABANDONED 2-13-92.

Produced by O. C. D. Artesia Office  
and by order of the Bureau of Land Management  
Bureau of Land Management

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title Production Supervisor

Date 2-15-92

(This space for Federal or State office use)

Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title \_\_\_\_\_

Date 2/26/92